 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: red;">74LS393 SOP5.2</h2>
	<p>Manufacturer Part Number: 74LS393 SOP5.2</p> <p>Manufacturer/Brand: HITACHI</p> <p>Part of Description: HITACHI SOP14-5.2</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 2200 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	




Specifications

Part Number	74LS393 SOP5.2
Manufacturer	HITACHI
Description	HITACHI SOP14-5.2
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2200 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

74LS393 SOP5.2 is New Original in Stock, Search 74LS393 SOP5.2 Datasheets, PDF, Inventory at Y-IC.com Online, Order 74LS393 SOP5.2 with warrantied and confidence. RFQ 74LS393 SOP5.2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>74LS38N MOT MOT DIP14</p>	 <p>74LS38P HIT HIT DIP14</p>	 <p>74LS393 CET CET DIP-14P</p>	 <p>74LS390N TI TI DIP</p>
 <p>74LS40N PHI PHI DIP14</p>	 <p>74LS404CD ST ST SOP</p>	 <p>74LS40 MAT MAT DIP</p>	 <p>74LS395AN TI TI DIP</p>

Hot Parts

[More](#)

- | | | | | |
|----------------------|-----------------------|----------------------------|-------------------------|---------------------|
| ⚙️ 02013A8R0DAT2A | ➡️ 08051C561K4Z2A | ➡️ 6MBP75RA060-55 | D AH183-WL-7 | ➡️ AOTF10T60 |
| ⚡️ APA100-101M | ⚙️ AT89LS53-12AC | D CC0402KRX7R6BB222 | ➡️ CGA2B2X5R1H471M050BA | ➡️ CRCW0201150KFNE0 |
| ⚙️ DD540N16K | ⚡️ FAN6752MYC | ⚙️ FPAL20SM6010 | ➡️ FQD4N25TM | ➡️ GB10RF60K |
| D GRM155C80J105ME15D | ⚙️ GRM1882C1H300JA01D | ⚡️ HLE-104-02-S-DV-BE-K-TR | ⚙️ IPP100N08N3G | ➡️ KD70F.20 |
| ➡️ LD1084D2T33R | ➡️ LE79R79-2DJC | ⚙️ LSP5527-S8A | ⚡️ LSP7606FA | ➡️ LT1785IS8#TRPBF |
| ➡️ LT3502AEDC#TRPBF | ➡️ LTC1562AIG#TRPBF | D LTM2883CY-3S#PBF | ⚙️ LVTB10S4896 | ⚡️ MAX3485EESA+T |
| ⚙️ MJD29CTF | D MLX90216GS | ➡️ MMSZ5236B-V-GS08 | ➡️ MP20046HN-LF-Z | ➡️ NJM1431AF-PAN |
| ⚡️ PI74FCT2244ATQX | ⚙️ PR1102-DR5 | ➡️ S-1155B15-U5T1U | ➡️ SI7949DP-T1-GE3 | ➡️ SKKL20-16E(D) |
| ⚙️ SMA6J40CA-TR | ⚡️ SRM20100LLTM70 | ⚙️ T481S20TNC | D TC554001AFT-85VT | ➡️ TYPE16P2X |
| ➡️ V24B24T200BS | ⚙️ V275LS10P | ⚡️ VE-JT1-MW | ⚙️ W1074YC200 | ➡️ ZXMC4559DN8TC |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited