

	<h2 style="color: red;">EL1881CS</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">EL1881CS</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Intersil</a>
	<b>Part of Description:</b>	IC VIDEO SYNC SEPARATOR 8-SOIC
<b>Datasheets:</b>	 <a href="#">EL1881CS.pdf</a>	
<b>RoHs Status:</b>	Contains lead / RoHS non-compliant	
<b>Stock Condition:</b>	New original, 448 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	<a href="#">EL1881CS</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC VIDEO SYNC SEPARATOR 8-SOIC
Category	<a href="#">Integrated Circuits (ICs) &gt; Linear - Video Processing</a>
Part Status	448 pcs Stock
Series	-
Mounting Type	Surface Mount
Type	Synchronous Separator
Applications	Drivers, Communications, PCMCIA
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Packaging	Tube

EL1881CS is New Original in Stock, Search EL1881CS Datasheets, PDF, Inventory at Y-IC.com Online, Order EL1881CS Intersil with warrantied and confidence. RFQ EL1881CS : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<p>In:</p>  <p><b>EL1881CSZ-T7</b> Intersil IC VIDEO SYNC SEPARATOR 8-SOIC</p>	 <p><b>EL1881CN</b> Intersil IC VIDEO SYNC SEPARATOR 8-DIP</p>	 <p><b>EL1881CSZ-T13</b> Intersil IC VIDEO SYNC SEPARATOR 8-SOIC</p>	 <p><b>EL1848IYZ</b> Intersil IC LED DRIVER RGLTR 400MA 8MSOP</p>
 <p><b>EL1848IYZ-T7</b> Intersil IC LED DRIVER RGLTR 400MA 8MSOP</p>	 <p><b>EL1881CS-T13</b> Intersil IC VIDEO SYNC SEPARATOR 8-SOIC</p>	 <p><b>EL1881CS-T7</b> Intersil IC VIDEO SYNC SEPARATOR 8-SOIC</p>	 <p><b>EL1881CSZ</b> Intersil IC VIDEO SYNC SEPARATOR 8SOIC</p>

### Hot Parts

[More](#)

- |                       |                    |                        |                      |                        |
|-----------------------|--------------------|------------------------|----------------------|------------------------|
| ⊛ 18087C471KAT2A      | ↔ 18125A822GAT2A   | ⇒ 22252C105MAT2A       | D 6MBP150RA-060      | ⇒ AD5453YUJ            |
| ↳ APT45M75JN          | ⊛ AT91RM9200CJ-100 | D ATTINY10-MAHR        | ⇒ BAS40WST/R         | ⇒ BDP949/SOT-223       |
| ⊛ BYM10-600-E3/96     | ↳ BZX55-C51        | ⊛ CGA4J3X5R1V684K125AB | ↔ CL03A105KQ3CSNC    | ⇒ CY283520CT           |
| D CY7C64113-PVCG      | ⊛ DMN5L06VK-7      | ↳ FSFR1800HSL          | ⊛ GCM1555C1H6R8DZ13D | ⇒ GRM1886T1H560JD01D   |
| ⇒ GRM32EB31A476KE20L  | ↔ HCNW4562-000E    | ⊛ ICL3232CPZ           | ↳ IR3500AMTRPBF.     | ⇒ LB11851TT-TLM-H      |
| ↔ LM22680MRX-ADJ/NOPB | ⇒ LMC6482IMX       | D LT1193CS8            | ⊛ LT1236BCS8-5#TRPBF | ↳ LT1236CCS8-5#TRPBF   |
| ⊛ M1010NC400          | D MC33163DWR2G     | ⇒ MMO75-12I01          | ↔ MPC972FA           | ⇒ NCP566ST12T3G        |
| ↳ OPA2132UA/2K5       | ⊛ PKFC05C-T75      | ↔ SH8K11MGATB          | ⇒ SP4062-04UTG       | ⇒ SPL134-1R2-R-1122    |
| ⊛ SSM6J212FE          | ↳ ST330C16L1       | ⊛ STK669-040           | D TLV2221CDBVRG4     | ⇒ TSL1315RA-680K3R0-PF |
| ↔ UC3717AQC           | ⊛ VI-242-CV        | ↳ VI-HAM-CM-09         | ⊛ XC17V04VQ44I       | ⇒ XCS10XL-4TQ144C      |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited