
 <p>A Renesas Company</p>	<p>X9313ZP</p>
	<p>Manufacturer Part Number: X9313ZP</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC XDCP 32-TAP 1K 3-WIRE 8-DIP</p> <hr/> <p>Datasheets: X9313ZP.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, 2399 pcs Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
 <p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X9313ZP
Manufacturer	Intersil
Description	IC XDCP 32-TAP 1K 3-WIRE 8-DIP
Category	Integrated Circuits (ICs) > Data Acquisition - Digital
Part Status	2399 pcs Stock
Series	XDCP™
Operating Temperature	0°C ~ 70°C
Features	-
Interface	Up/Down (U/D, INC, CS)
Configuration	Potentiometer
Tolerance	±20%
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Number of Circuits	1
Voltage - Supply	5V
Memory Type	Non-Volatile
Resistance (Ohms)	1k
Taper	Linear
Number of Taps	32
Temperature Coefficient (Typ)	±300 ppm/°C
Resistance - Wiper (Ohms) (Typ)	40
Packaging	Tube

X9313ZP is New Original in Stock, Search X9313ZP Datasheets, PDF, Inventory at Y-IC.com Online, Order X9313ZP Intersil with warrantied and confidence. RFQ X9313ZP : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X9313ZP-3 Intersil IC XDCP 32-TAP 1K 3-WIRE 8-DIP</p>	 <p>X9313ZPZ-3 Intersil IC XDCP 3-WIRE 32-TAP 10K 8DIP</p>	 <p>X9313ZMZ-3 Intersil IC XDCP 32-TAP 1K 3-WIRE 8-MSOP</p>	 <p>X9313ZPZ INTERASIL X9313ZPZ INTERASIL</p>
 <p>X9313ZMZ Intersil IC XDCP 32-TAP 10K 3-WIRE 8-MSOP</p>	 <p>X9313ZMZ-3T1 Intersil IC XDCP 32-TAP 1K 3-WIRE 8-MSOP</p>	 <p>X9313ZPI Intersil IC XDCP 32-TAP 1K 3-WIRE 8-DIP</p>	 <p>X9313ZMT1 Intersil IC XDCP 32-TAP 1K 3-WIRE 8-MSOP</p>

Hot Parts

[More](#)

- | | | | | |
|------------------------|----------------------|--------------------|-------------------------|----------------------|
| ⊛ 12101C105JAT2A | ↔ AD9201ARSZ-REEL | ⇒ AD9393BBCZ-80 | D AM29LV800B-120EI | ↗ AP3429KTTR-G1 |
| ⊣ AT24C128BN-SH-T | ⊛ B39871-B3793-Z810 | D BZX384C6V2-GS18 | ⇒ C1005X8R1H471M050BA | ↗ C1812X332K202 |
| ⊛ CGA4J1X7R1V225K125AC | ⊣ CM3403-46SO | ⊛ DD40F-20 | ↔ DSPIC33EP64MC506-I/MR | ↗ DSS9HB32E222Q91J |
| D DTC144EKA | ⊛ ESD7V0D5-TP | ⊣ FJX945GTF | ⊛ G1000QC400 | ↗ GD15PBT120L2S |
| ⇒ GRM1555C1E1R0BZ01D | ↔ GRM31CR60J476ME19K | ⊛ HZC15TRF-E | ⊣ IL388-HT | ↗ IR3843WMTR1PBF. |
| ↔ IRFB20N50KPBF | ⇒ IRG4BC20W-SPBF | D ISL95820CRTZ | ⊛ KA78M06TU | ⊣ LT1787HVHS8#TRPBF |
| ⊛ MB90562PFM-G-213-END | D MC78L06F-TP | ⇒ MLZ2012M4R7WT000 | ↔ NAU8402WG | ↗ NJU7016M |
| ⊣ NR4010T1R0N | ⊛ PCA24S08DP | ↔ PDG34V4B15NGW | ⇒ PS8302L-V-AX | ↗ PSND30E/10 |
| ⊛ S-80126CNMC | ⊣ S1D2506A01-D0B0 | ⊛ SCC68692E1 | D SI3586DV | ↗ SMV1255-004LF |
| ↔ TC74ACT04F | ⊛ TQM7M7012 | ⊣ TT106N06KOF | ⊛ VE-J60-CX/F2 | ↗ VS-12CWQ10FNTRR-M3 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited