







	<p>LB1939T</p>
	<p>Manufacturer Part Number: LB1939T</p> <p>Manufacturer/Brand: SANYO</p> <p>Part of Description: SANYO TSSOP</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 2500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	LB1939T
Manufacturer	SANYO
Description	SANYO TSSOP
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

LB1939T is New Original in Stock, Search LB1939T Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1939T with warrantied and confidence. RFQ LB1939T : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>LB1938T-TLM SANYO LB1938T-TLM SANYO</p>	 <p>LB1939T-TLM-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 20TSSOP</p>	 <p>LB1939TGEVB AMI Semiconductor / ON Semiconductor EVAL BOARD FOR LB1939T</p>	 <p>LB1939 SANYO SANYO SMD</p>
 <p>LB1938TGEVB AMI Semiconductor / ON Semiconductor BOARD EVAL LB1938T MOTOR DRIVER</p>	 <p>LB1939T-MPB-E AMI Semiconductor / ON Semiconductor IC BRIDGE DRIVER PAR TSSOP- 20</p>	 <p>LB1938FAGEVB AMI Semiconductor / ON Semiconductor EVAL BOARD H-BRIDGE MOTOR DVR</p>	 <p>LB1938T-TLM-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 8MSOP</p>

Hot Parts

More

- | | | | | |
|-------------------|--------------------|----------------------|----------------------|----------------------|
| ⊛ 06031A121KAT2A | ➔ 08052A120GAT2A | ➔ 2225SC153KAT1A\SB | D AC0402JRNPO9BN510 | ➔ AK5381XT-E2 |
| ⊣ AR7643-LF | ⊛ ATS137-WL-7-A | D B39881B9001C710S | ➔ BAV21W-7 | ➔ BR93LC46RF-WE2 |
| ⊛ BZG04-12TR | ⊣ CAT28F010NI-12 | ⊛ CC0805JRNPOABN680 | ➔ CY23S05SC-1T | ➔ D7ST501710KE |
| D ES1PA-E3/84A | ⊛ GP10G-E3/73 | ⊣ GRM1557U1H7R0DZ01D | ⊛ HAT2183WP-EL-E | ➔ HUF75329D3ST |
| ➔ IGC20F60GA | ➔ INA826AIDR | ⊛ IR3313S/AUIR3313S | ⊣ IRF1405ZS-7PTRRPBF | ➔ LM358PWR |
| ➔ LMH6723MAX | ➔ LMJ316BB7226KLHT | D LMSP43MA-271 | ⊛ LTC485MJ8 | ⊣ MAMF-010614-TR3000 |
| ⊛ MGA-87563 | D MURP200CT | ➔ RPR-0512RS | ➔ RT1402B7TR7 | ➔ RT9161A-50CX |
| ⊣ RTR040N03FM TTL | ⊛ SFH620A-1 | ➔ SI4704-C40-GMR | ➔ SI7772DP-T1-GE3 | ➔ SIL30C-12SADJ-HP4 |
| ⊛ ST7FMC1K4T3 | ⊣ SV36-3.3-150-1 | ⊛ T760S2600TTM | D T92S7D12-12-02 | ➔ TMK063CG1R2CP-F |
| ➔ TSM3460CX6 | ⊛ TUSB2551ARGTR | ⊣ VI-J2R-01 | ⊛ WSL25128L000FTA18 | ➔ WX171SF250 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited