
 <p>A Renesas Company</p>	<p>X5163P-2.7</p>
	<p>Manufacturer Part Number: X5163P-2.7</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 16K EE 8-DIP</p> <hr/> <p>Datasheets:  X5163P-2.7.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X5163P-2.7
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 16K EE 8-DIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.63V
Packaging	Tube

X5163P-2.7 is New Original in Stock, Search X5163P-2.7 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5163P-2.7 Intersil with warrantied and confidence. RFQ X5163P-2.7 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5163PI-2.7 Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>	 <p>X5163PI-2.7A Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>	 <p>X5163P Intersil IC CPU SUPRV 16K EE RST LO 8DIP</p>	 <p>X5163 INTERSI X5163 INTERSI</p>
 <p>X5163P-4.5A Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>	 <p>X5116ADSE-3C-E ELPIDA ELPIDA BGA</p>	 <p>X5163G Intersil X5163G INTERSIL</p>	 <p>X5163P-2.7A Intersil IC SUPERVISOR CPU 16K EE 8-DIP</p>

Hot Parts

More

- | | | | | |
|---|--|---|---|---|
| <ul style="list-style-type: none"> ⊕ 1SMC24AT3 ⊖ CBT6832EDGG ⊕ CY284160XCT D DT46N1200KOC ⇒ GRM0336T1E2R6CD01D ⇒ LTM4614EV#PBF ⊕ MOCD213R1M ⊖ PH150F48-5 ⊕ SMCJ45CA-E3/57T ⇒ TPS2010PWR | <ul style="list-style-type: none"> ⇒ AD2410WCCSZ ⊕ CC1206KKX7R5BB226 ⊖ D3507N800 ⊕ DZ23C16-GS08 ⇒ GRM2195C2A6R5DD01D ⇒ MAX707CSA-TG069 D ND410826 ⊕ QMK212B7222KD-T ⊖ SST49LF020A-33-4C-NH ⊕ TPS74801DRCRG4. | <ul style="list-style-type: none"> ⇒ ADP3300ARTZ-5.0-RL7 D CC1808KKX7RCBB222 ⊕ DG441LDY ⊖ EL2227CS-T7/T13 ⊕ HD64F2238RFA13V D MC3403DG ⇒ NRH3010T100M ⇒ RB751V-40TE-17 ⊕ TD122N16KOF ⊖ VBO125-18N07 | <ul style="list-style-type: none"> D ADS8323Y/2K ⇒ CNY17F33SD ⇒ DS1109SM40 ⊕ FFPF08S60SN ⊖ LB2016T101K ⊕ MC34064D-005 ⇒ OPA2336E ⇒ SGB8206ANT4G D TL062BIDT ⊕ VI-JT1-EZ | <ul style="list-style-type: none"> ⇒ C1005COG1H471F050BA ⇒ CY2081SL-113T ⇒ DS1337C#T&R ⇒ GRM0335C1E1R0BA01D ⇒ LM230-09 ⊖ MCR18EZPF27R0 ⇒ PDTA124XK ⇒ SLH2204-01 ⇒ TLV27L2CDGK ⇒ XC17S10PD8C |
|---|--|---|---|---|

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited