







	<p>LB1947</p>
	<p>Manufacturer Part Number: LB1947</p> <p>Manufacturer/Brand: SANYO</p> <p>Part of Description: LB1947 SANYO</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 673 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	LB1947
Manufacturer	SANYO
Description	LB1947 SANYO
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	673 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

LB1947 is New Original in Stock, Search LB1947 Datasheets, PDF, Inventory at Y-IC.com Online, Order LB1947 with warrantied and confidence. RFQ LB1947 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>LB1948M-TE-L-E SANYO LB1948M-TE-L-E SANYO</p>	 <p>LB1947VC-XE AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 15HZIP</p>	 <p>LB1948M-TE-LE SANYO SANYO SOP10</p>	 <p>LB1945H-TLM AMI Semiconductor / ON Semiconductor LB1945H-TLM ON</p>
 <p>LB1945H-TLM-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 28HSOP</p>	 <p>LB1947-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 13SIPHJ</p>	 <p>LB1946-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 28HDIP</p>	 <p>LB1945H-MPB-E AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR HSOP28H</p>

Hot Parts

More

- | | | | | |
|--------------------|----------------------|--------------------|--------------------|--------------------|
| ⊕ 08055A122KAT2A | ↔ 1808CC103JAT1A | ⇒ 1812CA392KAT1A | D 5STP17F2001 | ⇒ 5STP27L1200 |
| ⊖ AD7938BCPZ | ⊕ ADA-4743-TR2G | D ADN4662BRZ | ⇒ AXT434124 | ⇒ AZ2940D-1.2TRG1 |
| ⊕ BXA40-24S05 | ⊖ C0805C221J5GAC7800 | ⊕ CA383N2X11 | ↔ CAT24C128HU3IGT3 | ⇒ CMPWR300SA |
| D DBLS157GRD | ⊕ F16-100HIP | ⊖ FAN1582MX | ⊕ FQA65N06 | ⇒ G2R-24-24V |
| ⇒ ICL232CBE | ↔ KSZ8721B | ⊕ LFB322G45SN1A504 | ⊖ LM2902MX | ⇒ LT1060CN |
| ↔ LT3009ESC8#TRPBF | ⇒ MA3075WA-TX | D MAX3221IPWR | ⊕ MDA810-12N1 | ⊖ MP20046DQ-G-LF-Z |
| ⊕ MP26053DQ-LF-Z | D MP7731DF-LF-Z | ⇒ MSA-0185 | ↔ P4SMA170A | ⇒ PCD80703HL/B00/2 |
| ⊖ R5323Z023B-TR-FD | ⊕ RF1132TR7 | ↔ SA12A-E3/73 | ⇒ SD103R08S10PV | ⇒ SDED5-512M-N9T |
| ⊕ SI2305ADS-T1-GE3 | ⊖ STK65051MK3-Y2 | ⊕ SW04DXC32C | D T298N26TOF | ⇒ TC74VHC9541P |
| ↔ TCM810MENB713 | ⊕ TOP202YN | ⊖ TS824ILT-2.5 | ⊕ TTB6C110N12KOF | ⇒ V300C5T100B3 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited