









	<h2 style="color: red;">X5323S8-2.7T1</h2>	
	Manufacturer Part Number:	X5323S8-2.7T1
	Manufacturer/Brand:	Intersil
	Part of Description:	IC SUPERVISOR CPU 32K EE 8-SOIC
Datasheets:	 X5323S8-2.7T1.pdf	
RoHs Status:	Contains lead / RoHS non-compliant	
Stock Condition:	New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	X5323S8-2.7T1
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 8-SOIC
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.63V
Packaging	Tape & Reel (TR)

X5323S8-2.7T1 is New Original in Stock, Search X5323S8-2.7T1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323S8-2.7T1 Intersil with warrantied and confidence. RFQ X5323S8-2.7T1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>X5323S8-2.7A Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>	 <p>X5323S8-2.7AT1 Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>	 <p>X5323S8I Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>	 <p>X5323PZ-4.5A Intersil IC SUPERVISOR CPU 32K EE 8-DIP</p>
 <p>X5323S8I-2.7 Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>	 <p>X5323S8 Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>	 <p>X5323S8I-2.7AT1 Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>	 <p>X5323S8I-2.7A Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>

Hot Parts

[More](#)

<ul style="list-style-type: none"> ⚙️ APTB1615-CC28 ⚡ CD74HCT4067M ⚙️ DM818-800-45 D GRM32NF11C106ZA01L ⇒ KK25HB160 ⇒ LTC6091IUFE#PBF ⚙️ MMF200S060DA ⚡ RCLAMP0544T.TCT ⚙️ SB20200CT ⇒ TDA6111Q/N4 	<ul style="list-style-type: none"> ⇒ AT25256B-SSPD-T ⚙️ CMPT5087 ⚡ DS18B20U+T&R ⚙️ H11A3SVM ⇒ LA5797MC-BH ⇒ LVCO-2773T D NR6020TOR8N ⚙️ RT9198-34PV. ⚡ SD15C.TC ⚙️ TT215N04KOF 	<ul style="list-style-type: none"> ⇒ AT29C010A-90PI D CMSH2-20 ⚙️ DSILC6-4P6 ⚡ ICS3725G01L ⚙️ LE25FU206AMBW00TLM-H D M5M5256BFP-15 ⇒ PCHMB150B12 ⇒ S-1111B18PN-NYP-TF ⚙️ SI4848DY-T1 ⚡ VI-J30-IX 	<ul style="list-style-type: none"> D BSS123-NL ⇒ CX0805MRX7R0BB152 ⇒ DTC114EKAFT146 ⚙️ IPS1051LTRPBF. ⚡ LH28F160S3T-L10A ⚙️ MAX1249BEEE ⇒ PTFA081501E/1 ⇒ S-81246SGY D SUM110N06-3M9H-E3 ⚙️ VI-LU3-CV 	<ul style="list-style-type: none"> ⇒ BTA312-600B ⇒ DAC10GSZ ⇒ GQM2195C2E220JB12D ⇒ IRFH8316TRPBF. ⇒ LM1185SF5-1.5 ⚡ MIC5356-MMYMLTR ⇒ QM2518C1 ⇒ S-8211CDN-M5T1U ⇒ T85HFL60S05 ⇒ ZM4755A-GS18
--	--	--	---	---

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited