
 <p>A Renesas Company</p>	<h2 style="color: red;">X5163V14I-4.5A</h2>
	<p>Manufacturer Part Number: X5163V14I-4.5A</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 16K EE 14TSSOP</p> <hr/> <p>Datasheets:  X5163V14I-4.5A.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X5163V14I-4.5A
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 16K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.63V
Packaging	Tube

X5163V14I-4.5A is New Original in Stock, Search X5163V14I-4.5A Datasheets, PDF, Inventory at Y-IC.com Online, Order X5163V14I-4.5A Intersil with warrantied and confidence. RFQ X5163V14I-4.5A : Info@Y-IC.com

















You May Be Also Be interested

In:

 <p>X5163V14I Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163V14T1 Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163V14I-2.7 Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163V14I-2.7A Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>
 <p>X5163ZAN Intersil X5163ZAN INTERSIL</p>	 <p>X5163ZAL INTERSI X5163ZAL INTERSI</p>	 <p>X5163V14-4.5A Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p>X5163ZF Intersil X5163ZF INTERSIL</p>

Hot Parts

More

- | | | | | |
|--|--|---|---|---|
|  AD7886JP |  ADATE303XBCZ |  AP15T03H |  BS62LV4000STC-70 |  CBK-0515SF |
|  CDRH6D28NP-820NC |  CL21A106KQFNMF |  CSD17307Q5A |  DMN10H170SFDE-7 |  DP8570AV |
|  EDJ1116DJBG-GN-F-D |  EL5373IUZ |  GR8935LJG |  IRFR320TRR |  K4805/1000W |
|  LM26CIM5X-YPE |  LMV844QMT |  LT1013AMJ8 |  LT1619ES8#TRPBF |  LT3061EMS8E#PBF |
|  MA4P789CA-1146T |  MAX809SQ293D1T1G |  MBR12U100L-TP |  MC908QC8CDRE |  MCP1612-ADJI/MF |
|  MD1801SCG-TR |  MMVL229AT1G |  MOC3063SM |  NC7SP00L6X |  NSS12100M3T5G |
|  P589A1802 |  PI6C2404A-1WEX |  PP3-5-15 |  PRHMB100A6 |  RF2065TR7 |
|  S-812C33AUA |  S912XEQ384VAG |  SIR644DP-T1-GE3 |  SKD210/02 |  SKMD100/18E |
|  SMD030F-2018-2 |  SMD10P05L |  SMV1263-079LF |  T160N08BOF |  TL4050C25IDBZR |
|  TL780-05CKC |  UPG2404T6Q-E2-A |  V375A15T600AL2 |  VI-233-EX |  W180-03SZ |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited