


	<b>S-80844CLY-B-G</b>	
	<b>Manufacturer Part Number:</b>	S-80844CLY-B-G
	<b>Manufacturer/Brand:</b>	SII Semiconductor Corporation
	<b>Part of Description:</b>	IC VOLT DETECTOR 4.4V TO-92
	<b>Datasheets:</b>	 <a href="#">S-80844CLY-B-G.pdf</a>
	<b>RoHS Status:</b>	 Lead free / RoHS
	<b>Stock Condition:</b>	Compliant New original, Stock Available.
	<b>Ship From:</b>	Hong Kong
Image may be representation. See specs for product details.	<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS

### Specifications

Part Number	S-80844CLY-B-G
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 4.4V TO-92
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Through Hole
Type	Voltage Detector
Package / Case	TO-226-3, TO-92-3 (TO-226AA)
Supplier Device Package	TO-92-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	4.4V
Packaging	Bulk

S-80844CLY-B-G is New Original in Stock, Search S-80844CLY-B-G Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80844CLY-B-G SII Semiconductor Corporation with warranted and confidence. RFQ S-80844CLY-B-G : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>S-80844CLY-B2-U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V TO-92</p>	 <p><b>S-80844CLUA-B65T2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SOT89-3</p>	 <p><b>S-80844CLPF-B65TFG</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SNT-4A</p>	 <p><b>S-80844CLPF-B65TFU</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SNT-4A</p>
 <p><b>S-80844CNMC-B85T2G</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SOT23-5</p>	 <p><b>S-80844CNMC-B85T2U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V SOT23-5</p>	 <p><b>S-80844CLUA-B65-T2</b> SEIKO S-80844CLUA-B65-T2 SEIKO</p>	 <p><b>S-80844CLY-Z2-U</b> SII Semiconductor Corporation IC VOLT DETECTOR 4.4V TO-92</p>

### Hot Parts

More

- |                    |                    |                    |                       |                      |
|--------------------|--------------------|--------------------|-----------------------|----------------------|
| 12061Z475MAT2A     | ALM-GA001-TR1G     | AMC1117-3.3SJ      | AT45DB041D-SU         | BA7653AF-E2          |
| BCM7401D1KPB1G     | BK60A-048L-050F30H | BZM55C39           | CD74HCT221E           | CGJ3E2C0G1H6R8D080AA |
| CMF6522R000FKEK    | CY28346ZC          | DMN1025UFDB-7      | DMN6140LQ-7           | G6B-2214P-US-12VDC   |
| GCM32ER71E106KA14F | GRM1887U2A9R7DZ01D | GRM21BR60J475KA11K | HAL509SF-A-4-R        | ISL6729IBZ           |
| KSD73YTU           | LFB321G66SB1-560   | LM2853MH-1.8/NOPB  | LM95241C1MM-2         | LM98722CCMTX/NOPB    |
| MCH39147-8-TL      | MJE13001C1         | MMSZ4687-V         | MN1382TP              | NL17SZ02DFT2G        |
| NTMFS4846          | P16K-5/4           | P545A2017          | PE-65968T             | PQ20RX11J00H         |
| RF1622TR7          | RT9161B-33PX       | S9S12G96F0MLH      | SAK-TC1797-512F180EAC | SD300N32PSC          |
| SN75C188D          | T1039N20           | TD105N06KOF        | TDA7274D              | TPS65050RSMR         |
| TYPEOB30/15        | VI-B5V-CV          | VI-J6V-MZ          | VNQ5050AKTR-E         | XRP6141EL-F          |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited