

	MPC93R52FA
	Manufacturer Part Number: MPC93R52FA
	Manufacturer/Brand: NXP Semiconductors / Freescale
	Part of Description: IC CLOCK GEN 1:11 PLL LV 32-LQFP
<p>Image may be representation. See specs for product details.</p>	Datasheets:  MPC93R52FA.pdf
	RoHs Status: Contains lead / RoHS non-compliant
	Stock Condition: New original, Stock Available.
	Ship From: Hong Kong
	Shipment Way: DHL/Fedex/TNT/UPS/EMS

Specifications	
Part Number	MPC93R52FA
Manufacturer	NXP Semiconductors / Freescale
Description	IC CLOCK GEN 1:11 PLL LV 32-LQFP
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Type	Clock Driver, Clock Generator, Fanout Distribution,
Frequency - Max	240MHz
Package / Case	32-LQFP
Supplier Device Package	32-LQFP (7x7)
Number of Circuits	1
Voltage - Supply	3.135 V ~ 3.465 V
Output	LVC MOS
Input	LVC MOS
PLL	Yes with Bypass
Ratio - Input:Output	1:11
Differential - Input:Output	No/No
Divider/Multiplier	Yes/No
Packaging	Tray

MPC93R52FA is New Original in Stock, Search MPC93R52FA Datasheets, PDF, Inventory at Y-IC.com Online, Order MPC93R52FA NXP Semiconductors / Freescale with warrantied and confidence. RFQ MPC93R52FA : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MPC940LAC NXP Semiconductors / Freescale IC CLOCK DIST CHIP 1:18 32-LQFP</p>	 <p>MPC93R52AC IDT (Integrated Device Technology) IC CLK GEN ZD 1:11 32-LQFP</p>	 <p>MPC93R52ACR2 IDT (Integrated Device Technology) IC CLK GEN ZD 1:11 32-LQFP</p>	 <p>MPC940L MOT MPC940L MOT</p>
 <p>MPC93R51ACR2 IDT (Integrated Device Technology) IC PLL CLK DRIVER LV 32-LQFP</p>	 <p>MPC93R51AC NXP Semiconductors / Freescale IC PLL CLOCK DRIVER LV 32-LQFP</p>	 <p>MPC940LAC IDT (Integrated Device Technology) IC CLK FANOUT BUFFER 1:18 32LQFP</p>	 <p>MPC93R51FA NXP Semiconductors / Freescale IC PLL CLOCK DRIVER LV 32-LQFP</p>

Hot Parts

More

- | | | | | |
|-------------------------|------------------------|-----------------------|-----------------------|-----------------------|
| ⚙️ 12063A150JAT2A | ➡️ 12102U391FAT4A | ➡️ ADP3309ARTZ-3.3-RL | D BAW567DW-7-F | ➡️ BSM22GD101D |
| ⊖ BTB06-600TRG | ⚙️ C1608X7R1H103J | D CC1010PAG | ➡️ CC1206JRNPOABN681 | ➡️ CDF75A-080 |
| ⚙️ CGJ5H2C0G1H473J115AA | ⊖ CL21C040CBANNNC | ⚙️ DS34C87TM | ➡️ FDMC7680 | ➡️ FM25CL64B-GTR |
| D FMMT560TA | ⚙️ GPDS200A-054B-HL081 | ⊖ GRM152R60J104KE19D | ⚙️ IHLP2525CZRZ4R7M01 | ➡️ IRKH196/14 |
| ➡️ ISL6559CB-T. | ➡️ LT1016CS8#TRPBF | ⚙️ LT1252CN8 | ⊖ LT1763CS8-1.8#TRPBF | ➡️ MABA-010408-CF1160 |
| ➡️ MAX8939BEWV+T | ➡️ MB81G83222-012PQ-A | D MC10EL16DR2 | ⚙️ MDD55A12 | ⊖ MG30N2YK1 |
| ⚙️ MXD1815UR29+T | D OPA2134UA/2K5 | ➡️ P189A2003 | ➡️ PDH15016A | ➡️ PIC18F1320-I/SS |
| ⊖ PKG4627PI | ⚙️ PSD61/12 | ➡️ PT28C020P-90 | ➡️ PVM4A102C01R00 | ➡️ QM50DY-HB |
| ⚙️ RV4141AN | ⊖ SC14441B52RLT | ⚙️ SFH6135-X007T | D SKD230/18 | ➡️ SMDJ75CA |
| ➡️ STGP10NB60SFP | ⚙️ STM32F030R8T6 | ⊖ TPS2816DBVR | ⚙️ TPS53125PWRG4 | ➡️ VE-251-CU |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited