









 <p>A Renesas Company</p>	<p>ISL3158AEMBZ-T</p>
	<p>Manufacturer Part Number: ISL3158AEMBZ-T</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC TXRX RS422/485 10MBPS 8SOIC</p> <p>Datasheets: ISL3158AEMBZ-T.pdf</p> <p>RoHS Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	ISL3158AEMBZ-T
Manufacturer	Intersil
Description	IC TXRX RS422/485 10MBPS 8SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-55°C ~ 125°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Voltage - Supply	4.5 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Half
Receiver Hysteresis	20mV
Data Rate	10Mbps
Packaging	Tape & Reel (TR)

ISL3158AEMBZ-T is New Original in Stock, Search ISL3158AEMBZ-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL3158AEMBZ-T Intersil with warrantied and confidence. RFQ ISL3158AEMBZ-T : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ISL3156EUIZ-T Intersil IC TXRX RS422/485 20MBPS 10MSOP</p>	 <p>ISL3158AEMBZ-T7A Intersil IC TXRX RS422/RS485 8SOIC</p>	 <p>ISL3158EIBZ-T Intersil IC TXRX RS422/485 10MBPS 8SOIC</p>	 <p>ISL3158AEMBZ Intersil IC TXRX RS422/485 10MBPS 8SOIC</p>
 <p>ISL3158EIBA INTERSIL INTERSIL SOP8</p>	 <p>ISL3158EIBZ Intersil IC TXRX RS422/485 10MBPS 8SOIC</p>	 <p>ISL3156EIBZ-T7A Intersil IC TXRX RS422/RS485 14SOIC</p>	 <p>ISL3156EUIZ Intersil IC TXRX RS422/485 20MBPS 10MSOP</p>

Hot Parts

More

- | | | | | |
|-------------------------|----------------------|----------------------|------------------------|-------------------|
| ⊛ 1551572-5 | ↔ 1812AA561KAT1A\SB | ⇒ 293D337X06R3E2TE3 | D 6DI10A-050/ | ⇒ 6SEPC470MX |
| ⊣ A50L-0001-0303 | ⊛ AIC1642-50PX | D APS2408E55-ADJ | ⇒ AT17LV010A-10JC | ⇒ BB439E6327 |
| ⊛ BYVB32-50 | ⊣ CHM3E-32000073 | ⊛ CL21C180JBANNND | ↔ DB2F200N4 | ⇒ DE2S06800L |
| D DSPIC33FJ16MC304-E/PT | ⊛ DZ2S270M0L | ⊣ FA38SA50LC | ⊛ FM32L276-GTR | ⇒ FQD2N50TF |
| ⇒ GCM1885C2A3R9CA16D | ↔ GJM0335C1E9R3DB01D | ⊛ GRM21A7U2E181JW31D | ⊣ HMC309MS8G | ⇒ IPB017N06N3G |
| ↔ IRL3705ZS | ⇒ LM49200TLX | D LTC3403EDD#\TRPBF | ⊛ MIC2211-2.8/3.3BMLTR | ⊣ MMBT3906LT1G |
| ⊛ MT8962AS | D NCP303LSN44T1 | ⇒ NJU7741F28 | ↔ NL453232T-4R7J | ⇒ NLC322522T-820J |
| ⊣ NRH3012T150MN | ⊛ NTB4302G | ↔ NTR3C21NZT1G | ⇒ PT8A974PE | ⇒ PTH12060WAH |
| ⊛ R1271NS08E | ⊣ R1279NS22L | ⊛ S-8261ABMMD-G3M-T2 | D S99AL016DBT1 | ⇒ SBR20A120CTFP-G |
| ↔ SI7216DN-T1-E3 | ⊛ SN74HC02ADBR | ⊣ STW9NK60Z | ⊛ UMK105CG080DV-F | ⇒ UMK105CH070FW-F |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited