
 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">X5083P-4.5A</h2>
	<p><b>Manufacturer Part Number:</b> <a href="#">X5083P-4.5A</a></p> <hr/> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <hr/> <p><b>Part of Description:</b> IC SUPERVISOR CPU 8K EE 8-DIP</p> <hr/> <p><b>Datasheets:</b>  <a href="#">X5083P-4.5A.pdf</a></p> <hr/> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <hr/> <p><b>Stock Condition:</b> New original, Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









### Specifications

Part Number	X5083P-4.5A
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 8K EE 8-DIP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Through Hole
Type	Simple Reset/Power-On Reset
Package / Case	8-DIP (0.300", 7.62mm)
Supplier Device Package	8-PDIP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.63V
Packaging	Tube

X5083P-4.5A is New Original in Stock, Search X5083P-4.5A Datasheets, PDF, Inventory at Y-IC.com Online, Order X5083P-4.5A Intersil with warrantied and confidence. RFQ X5083P-4.5A : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <p><b>X5083P-2.7</b> Intersil IC SUPERVISOR CPU 8K EE 8-DIP</p>	 <p><b>X5083P</b> Intersil IC CPU SUPRV 8K EE RST LO 8DIP</p>	 <p><b>X5083P-2.7A</b> Intersil IC SUPERVISOR CPU 8K EE 8-DIP</p>	 <p><b>X5083PIZ</b> Intersil IC CPU SUPERV 8K EEPROM 8DIP</p>
 <p><b>X5083PI-2.7A</b> Intersil IC SUPERVISOR CPU 8K EE 8-DIP</p>	 <p><b>X5083PI-2.7</b> Intersil IC SUPERVISOR CPU 8K EE 8-DIP</p>	 <p><b>X5083PI-4.5A</b> Intersil IC SUPERVISOR CPU 8K EE 8-DIP</p>	 <p><b>X5083I</b> SOP-8 X5083I SOP-8</p>

### Hot Parts

[More](#)

- |                   |                    |                    |                      |                  |
|-------------------|--------------------|--------------------|----------------------|------------------|
| 04023A8R2CAT2A    | 22205C125KAT1A     | ADM1027ARQZ        | ADR370BRTZ-REEL7     | AP061A180JQT2A   |
| APT5012JVFR       | BB178+115          | BSS138W-7-F        | C0603C0G1H2R2C030BA  | CD74HCT164M96    |
| CS0603KRX7R9BB473 | CX06827-13         | CY2292SC-474T      | FCB20N60F            | FDW2520C         |
| FSA4159P6X        | FTZ953TA           | GRM31CR61H225KA88L | GRM31CR71A226ME15L   | HD6433800A20H    |
| IDTQS3861Q        | IHLM2525CZER1R5M01 | ISC1210ER680K      | LM2903DR2            | MAZ8082UML       |
| MC1610V0R85R05    | MCR006MZPEJ122     | ME501610           | MMBZ5239BLT1         | MP2144GJ         |
| NH2-500V          | NRS6045T3R0NMGK    | P080PH14FH0        | PM96D05N             | SI4952DY-T1-GE3  |
| SIHF18N50D        | SKBT28/14          | SKM22GD124D        | STB15NM65N           | SY89833LMGTR     |
| TS5A26542YZTR     | UBA2081T/1         | UP0431400L         | UPD78F1142AGB-GAH-AX | V110C15T100BG    |
| V48V48C150BL      | VE-26L-IY          | VI-B60-IV-10       | VI-J6P-MY            | XC9536XL-7VQG44C |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited