


 <p>A Renesas Company</p>	<p><b>ISL88001IE22Z-T7A</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ISL88001IE22Z-T7A</a></p> <hr/> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <hr/> <p><b>Part of Description:</b> IC VOLT SUPERVISOR 2.19V SC70-3</p> <hr/> <p><b>Datasheets:</b>  <a href="#">ISL88001IE22Z-T7A.pdf</a></p> <hr/> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <hr/> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









### Specifications

Part Number	<a href="#">ISL88001IE22Z-T7A</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC VOLT SUPERVISOR 2.19V SC70-3
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-70, SOT-323
Supplier Device Package	SC-70-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	2.19V
Packaging	Tape & Reel (TR)

ISL88001IE22Z-T7A is New Original in Stock, Search ISL88001IE22Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88001IE22Z-T7A Intersil with warrantied and confidence.  
RFQ ISL88001IE22Z-T7A : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <p><b>ISL88001IE26Z-T</b> Intersil IC VOLT SUPERVISOR 2.63V SC-70</p>	 <p><b>ISL88001IE22Z-TK</b> Intersil IC VOLT SUPERVISOR 2.19V SC-70</p>	 <p><b>ISL88001IE23Z-T7A</b> Intersil IC VOLT SUPERVISOR 2.32V SC70-3</p>	 <p><b>ISL88001IE23Z-T</b> Intersil IC VOLT SUPERVISOR 2.32V SC-70</p>
 <p><b>ISL88001IE18Z</b> INTERSI ISL88001IE18Z INTERSI</p>	 <p><b>ISL88001IE23Z-TK</b> Intersil IC VOLT SUPERVISOR 2.32V SC-70</p>	 <p><b>ISL88001IE22Z-T</b> Intersil IC VOLT SUPERVISOR 2.19V SC-70</p>	 <p><b>ISL88001IE17Z-T</b> Intersil IC VOLT SUPERVISOR 1.67V SC-70</p>

### Hot Parts

[More](#)

- |  |  |   |  |   |
|--|--|---|--|---|
|  08052C332KAT2A     |  08055C103KAZ2A     |  2225CC184KAT3A SB   |  D 5SDD71X0400     |  AAT3218IGV-1.8  |
|  AIH10H300 N        |  AS222-92           |  D CC0805ZRY5V8BB334 |  CC1206FRNPO9BN101 |  CD74ACT652EN    |
|  CDRH127/LDNP-470MC |  CL05A475MP5NRNC    |  DD241S14K           |  DFLZ11-7-F        |  DMN10H120SE     |
|  D FAN5602MP45X     |  FDB070AN06A0       |  FZT704TA            |  HAT200-S          |  HAT3036R        |
|  IMP706PCPA         |  IPW65R095C7        |  IXFK64N60P          |  LBC2518T100K      |  LMV981MGX/NOPB  |
|  MBR2X160-45        |  MCC26-12I08        |  D MRMS203A          |  MVR22HXBRN333     |  NAND128W3A2BN6E |
|  NJM2403V           |  D NQE7320MC        |  P1803ABL            |  PD150-N0018       |  PS1117-25       |
|  RN1102MFV          |  S-80848CNUA-B89T2G |  SAK-TC1767-256F80   |  SC507125YDWR2     |  SMBJ13CA        |
|  SN74LVC3G04YZPR    |  SS13HE3/5AT        |  T1250H-6T           |  D THS4281DGKR     |  TPS826716SIPT   |
|  UM1512-01W         |  VI-J6T-MX          |  XC2V1000-4FGG456I   |  XC61CC4002PR      |  ZCAT3618-2630D  |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited