
 <p>A Renesas Company</p>	<h2 style="color: #C00000;">X5323V14</h2>	
	<p>Manufacturer Part Number: X5323V14</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC SUPERVISOR CPU 32K EE 14TSSOP</p> <hr/> <p>Datasheets:  X5323V14.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>	
<p>Image may be representation. See specs for product details.</p>		








Specifications

Part Number	X5323V14
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tube

X5323V14 is New Original in Stock, Search X5323V14 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323V14 Intersil with warrantied and confidence. RFQ X5323V14 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5323V14-2.7A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14I Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323V14-2.7T1 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323S8Z-4.5 XICOR X5323S8Z-4.5 XICOR</p>
 <p>X5323S8ZT1 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5323V14-2.7 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5323S8Z-4.5A Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5323S8Z-2.7T1 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>

Hot Parts

More

- | | | | | |
|--------------------|-----------------------|--------------------|----------------------|-----------------|
| 06032U5R1BAT2A | 06033C392J4T2A | 1206ZD685KAT2A | A3142EUA-T | AD8632ARA |
| AD96S08KDF | ATAR0920-085-TKQH | BKO-NC5363HOZ | CGJ3E2C0G1H332J080AA | CLN-50SP1 |
| CNSF161-002 | DSPIC33FJ32MC202-E/MM | ESD8004MUTAG | EZ1587CM-TR | FDC6312P |
| D FQA33N10L | GRM1885C1H7R2DZ01D | GRM2196P2A300JZ01D | HIP6601CAB | IRF7301TR |
| IRL3102S | ISL62773HRZ-T | LB11698H-TE-L | LC9009CB3TR263DN | LD39150DT33-R |
| LFB2H2G59SG7B858 | LM3046MX/NOPB | LMV614MTX/NOPB | LT3021EDH-1.8#PBF | MHW806A4 |
| MIC5182YM | MM74HC138MX | NCP1654BD133R2G | P370KH06 | PE-1008CM561JTT |
| PM20CEF060-31 | R1200CH04FK0 | R6000230XXYA | RB068MM-60TR | RT8152CGQW |
| S-1112B48MC-L7HTFG | SiL154CT64 | SMCJ350CA | STS2306-1 | TEPSLA1A336B8R |
| TZA3047AVH/C1 | UC2879DWTRG4 | USB2512BI-AEZG | VI-26Y-EU | VI-J71-EZ/S |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited