

	<h2 style="color: red;">S-875087FUP-AKA-T2</h2>
	<p>Manufacturer Part Number: S-875087FUP-AKA-T2</p> <p>Manufacturer/Brand: SEIKO</p> <p>Part of Description: SEIKO SOT-89</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 4500 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	S-875087FUP-AKA-T2
Manufacturer	SEIKO
Description	SEIKO SOT-89
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	4500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

S-875087FUP-AKA-T2 is New Original in Stock, Search S-875087FUP-AKA-T2 Datasheets, PDF, Inventory at Y-IC.com Online, Order S-875087FUP-AKA-T2 with warrantied and confidence.
RFQ S-875087FUP-AKA-T2 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-875087FUP-AKAT2U SII Semiconductor Corporation IC REG LINEAR 5V SOT89-5</p>	 <p>S-875087EUP-AJGT2G SII Semiconductor Corporation IC REG LINEAR 5V SOT89-5</p>	 <p>S-875077EUP-AJFT2G SII Semiconductor Corporation IC VOLT DETECT/REG 5.0V SOT89-5</p>	 <p>S-875087FUP-AJAT2G SII Semiconductor Corporation IC VOLT DETECT/REG 5.0V SOT89-5</p>
 <p>S-8750B0CUP-ACGT2U SII Semiconductor Corporation IC REG LINEAR 5V SOT89-5</p>	 <p>S-875087EUP-AJGT2U SII Semiconductor Corporation IC REG LINEAR 5V SOT89-5</p>	 <p>S-8750B0CUP-ACG-T2G SEIKO SEIKO SOT89-5</p>	 <p>S-875087FUP-AKAT2G SII Semiconductor Corporation IC REG LINEAR 5V SOT89-5</p>

Hot Parts

[More](#)

- | | | | | |
|---------------------|-------------------------|-------------------|--------------------|--------------------|
| ⚙️ 06031A360GAT2A | ➡️ 12065C223JAT7A | ➡️ 18121C225K4T2A | D 183NQ100 | ➡️ AD8314ACPZ |
| ⊖ BL-HGE35A-TRB | ⚙️ CGA2B3X7R1V473K050BB | D CL21B474KBFNNNF | ➡️ D405SH16 | ➡️ DA807-880-26 |
| ⚙️ DS1073Z-100 | ⊖ DSSK60-015A | ⚙️ DT106N12K | ➡️ F25L008A-100 | ➡️ FDD86113LZ |
| D FQPF13N50CF | ⚙️ HS-PKD033V4B15GW | ⊖ HSMS-282K-TR1 | ⚙️ IPS6011RPBF | ➡️ LB8352LPL-TLM-E |
| ➡️ LP5904TMX-3.1 | ➡️ LTC2860IGN#TRPBF. | ⚙️ MA3XD1100L | ⊖ MAX4053ESE+ | ➡️ MIC5019YFT-TR |
| ➡️ ML4824CS-2 | ➡️ NSR02L30NXT5G | D NSR20F20NXT5G | ⚙️ OPA4277MDTEP | ⊖ PS48H12CF2 |
| ⚙️ PT8A977P | ➡️ QTLP670CY7751D | ➡️ R3636EC16M | ➡️ RN4907FE | ➡️ RSR015P03TL |
| ⊖ S71WS128PC0HH3SR0 | ⚙️ SKKT131/12D | ➡️ SKN2M240/18 | ➡️ SMF75A_R1_00001 | ➡️ SML60EUZ06JD-T |
| ⚙️ SQ4401EY | ⊖ SQCB71M150JAT1A | ⚙️ STPS120M | D TDA7073AT | ➡️ TK18A50D |
| ➡️ TL1451ACDR | ⚙️ TPS65913B3BEYFFR | ⊖ TSR50AA40 | ⚙️ VI-811288 | ➡️ WRM0207C-680KFI |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited