


	<p>S-80838CNNB-B8XT2U</p>
	<p>Manufacturer Part Number: S-80838CNNB-B8XT2U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 3.8V SC-82AB</p>
	<p>Datasheets:  S-80838CNNB-B8XT2U.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-80838CNNB-B8XT2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 3.8V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	3.8V
Packaging	Original-Reel®

S-80838CNNB-B8XT2U is New Original in Stock, Search S-80838CNNB-B8XT2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80838CNNB-B8XT2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80838CNNB-B8XT2U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80838CNNB-B8X-T2G SEIKO SEIKO SOT323-4</p>	 <p>S-80838CNNB-B8X-T2 SEIKO SEIKO SOT-343</p>	 <p>S-80838CNMC-B8XT2U SII Semiconductor Corporation IC VOLT DETECTOR 3.8V SOT23-5</p>	 <p>S-80838CNUA-B8XT2U SII Semiconductor Corporation IC VOLT DETECTOR 3.8V SOT89-3</p>
 <p>S-80838CNUA-B8X-T2 SEIKO SEIKO SOT-89</p>	 <p>S-80838CNPF-B8XTFU SII Semiconductor Corporation IC VOLT DETECTOR 3.8V SNT-4A</p>	 <p>S-80838CNNB-B8XT2G SII Semiconductor Corporation IC VOLT DETECTOR 3.8V SC-82AB</p>	 <p>S-80838CNUA-B8XT2G SII Semiconductor Corporation IC VOLT DETECTOR 3.8V SOT89-3</p>

Hot Parts

More

- | | | | | |
|------------------------|--------------------|----------------------|-----------------------|----------------------|
| ⊕ 06035A821FAT2A | ↔ 6MBP15RY060-01 | ⇒ ACT8930QJ134-T | D AP1084D33G-13 | ⇒ BZX384C13 |
| ⊖ C0603C0G1E0R9B030BF | ⊕ CDSOD323-T245C | D CDT90-12 | ⇒ CNY17GF-2SD | ⇒ DIM1600FSM17-A |
| ⊕ DMN4034SSD-13 | ⊖ ECH8663R-TL-H | ⊕ EL5205ISZ | ↔ EMH2314-TL-H | ⇒ EMK107BJ224KAHT |
| D ES3-P05-17 | ⊕ FAN2508S30X | ⊖ FP75R06KE3_B13ENG | ⊕ GAL22V10D-25LPNI | ⇒ GJM1555C1H3R9CB01D |
| ⇒ HCPL-0631 | ↔ IRF4905LPBF. | ⊕ IRF6892STRPBF | ⊖ IRFP3710 | ⇒ IRFR2405TRPBF. |
| ↔ LC4128ZC-75MN2-42 | ⇒ LC7461-8103 | D LD05YC475KAB2A\500 | ⊕ LD061A330KAB2A | ⊖ LQW31HN8N8J03L |
| ⊕ LTC4057ES5-4.2#TRPBF | D M50FLW080AN5TG | ⇒ MAX1762EUB-T | ↔ MC74VHCT573ADTRG | ⇒ MUR2020FCT |
| ⊖ NLC322522T-331K | ⊕ OPA2211AIDRGR | ↔ PDMB150B12C2 | ⇒ PIC24FJ64GA008-I/PT | ⇒ PT7M8202B25C5E |
| ⊕ RC1210JR-0710K-10K | ⊖ S-5711ANDL-I4T1G | ⊕ S-8211AAR-M5T1G | D S556-5999-32 | ⇒ SKD31/12 |
| ↔ SMAJ13CA-13-F | ⊕ SMAJ6.5CA-13-F | ⊖ UC3875QPTR | ⊕ VT234WFQX-ADJ | ⇒ W631GU6KB-15 |

Contact us: **Info@Y-IC.com**

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited