
 <p>A Renesas Company</p>	<p><b>X5168V14I-2.7T1</b></p>
	<p><b>Manufacturer Part Number:</b> X5168V14I-2.7T1</p> <p><b>Manufacturer/Brand:</b> Intersil</p> <p><b>Part of Description:</b> IC SUPERVISOR CPU 16K EE 14TSSOP</p> <p><b>Datasheets:</b>  <a href="#">X5168V14I-2.7T1.pdf</a></p> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <p><b>Stock Condition:</b> New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	X5168V14I-2.7T1
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 16K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.63V
Packaging	Tape & Reel (TR)

X5168V14I-2.7T1 is New Original in Stock, Search X5168V14I-2.7T1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5168V14I-2.7T1 Intersil with warrantied and confidence. RFQ X5168V14I-2.7T1 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

In:

 <p><b>X5168V14T1</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p><b>X5168V14I-2.7A</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p><b>X5168ZF</b> INTERSI X5168ZF INTERSI</p>	 <p><b>X5168V14I-4.5A</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>
 <p><b>X5168V14I</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p><b>X5168V14-4.5A</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p><b>X5168V14IT1</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>	 <p><b>X5168V14I-2.7</b> Intersil IC SUPERVISOR CPU 16K EE 14TSSOP</p>

### Hot Parts

More

- |   |  |  |  |   |
|---|--|--|--|---|
|  0805YC821KAT2A      |  120782-DD85N       |  ADC0817CCN           |  AP50T10GP-HF  |  AR904P03                |
|  AXK734247G          |  BH28FB1WHFV-GTR    |  CGA6P4C0G2J333J250AA |  DS1819CR-5    |  DSP56ADC16S             |
|  DTC143ZETL          |  FB2520-10E2R4AT/LF |  FDN361AN-NL          |  FSMLF327      |  GCM21A7U2E331JX01D      |
|  D QM1875C2E3R0WB12D |  GRM1555C2A6R1DA01J |  HCPL0531R2           |  IRFK2D45      |  LC4128V-75T100C-10T100I |
|  LM324DR2            |  LM3674MFX-ADJ      |  LM7915CT             |  LT1308BIS8    |  LTC4267IGN-1#PBF        |
|  M0130SL220          |  MBRF20U65CT-U/P    |  D NGB8206ANTF4G      |  OF70HA100D    |  P0751.332T              |
|  P6KE200A-E3/73      |  PCA9554DB          |  PI2BV3867QX          |  QM3024M3      |  SAFEA2G35MF0F0AR15      |
|  SB05-03C            |  SD14-150           |  SKR141F15            |  SMBJ14A-E3/52 |  SMBT1294LT3             |
|  SR170L-6S           |  ST78L05U           |  STD17NF03T4          |  D TB3500M-13  |  TL084MDT                |
|  USB3740B-AI2-TR     |  VE-262-EU          |  VE-272-MX            |  VI-224-CV     |  XP0431N00L              |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited