


 <p>A Renesas Company</p>	<p><b>ISL88001IE22Z-T</b></p>
	<p><b>Manufacturer Part Number:</b> ISL88001IE22Z-T</p> <p><b>Manufacturer/Brand:</b> Intersil</p> <p><b>Part of Description:</b> IC VOLT SUPERVISOR 2.19V SC-70</p> <p><b>Datasheets:</b>  <a href="#">ISL88001IE22Z-T.pdf</a></p> <p><b>RoHs Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	


### Specifications

Part Number	ISL88001IE22Z-T
Manufacturer	Intersil
Description	IC VOLT SUPERVISOR 2.19V SC-70
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-70, SOT-323
Supplier Device Package	SC-70-3
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	140 ms Minimum
Voltage - Threshold	2.19V
Packaging	Tape & Reel (TR)

ISL88001IE22Z-T is New Original in Stock, Search ISL88001IE22Z-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL88001IE22Z-T Intersil with warrantied and confidence. RFQ ISL88001IE22Z-T : Info@Y-IC.com

### You May Be Also Be interested

In:



Not Actual Photo  
YIC International Co., Limited.

<p><b>ISL88001IE18Z</b> Intersil IC VOLT SUPERVISOR 1.58V SC-70</p>	<p><b>ISL88001IE16Z-TK</b> Intersil IC VOLT SUPERVISOR 1.58V SC-70</p>	<p><b>ISL88001IE22Z-T7A</b> Intersil IC VOLT SUPERVISOR 2.19V SC70-3</p>	<p><b>ISL88001IE17Z-T</b> Intersil IC VOLT SUPERVISOR 1.67V SC-70</p>
<p><b>ISL88001IE22Z-TK</b> Intersil IC VOLT SUPERVISOR 2.19V SC-70</p>	<p><b>ISL88001IE17Z-T7A</b> Intersil IC VOLT SUPERVISOR 1.67V SC70-3</p>	<p><b>ISL88001IE23Z-T7A</b> Intersil IC VOLT SUPERVISOR 2.32V SC70-3</p>	<p><b>ISL88001IE23Z-T</b> Intersil IC VOLT SUPERVISOR 2.32V SC-70</p>

### Hot Parts

More

- |                      |                    |                     |                 |                     |
|----------------------|--------------------|---------------------|-----------------|---------------------|
| 04025A1R2DAT2A       | 12102A102FAT2A     | 13005-92-ECB        | D 25TTS12S      | ADS7846IPWR         |
| AP1512K5L-13         | AZ2015-04C.R7G     | D BYV133-45         | BZD27C22P-E3-08 | C0603X7R1A472K030BA |
| CC0805JRNPO0BN180    | DMN15H310SE-13     | DS1314E+TR          | EL9112ILZ       | GRM0225C1E2R0WA03L  |
| D GRM1555C1E8R3CA01D | GRM1556P1H2R9CZ01D | GRM188R61A475KAAJD  | HGTP20N60A4     | HS126150            |
| HUFA76633S3S         | HV2701FG-G         | INA146UA            | LM2476TB        | LP5907MF-1.2/NOPB   |
| MC74ACT74DR2         | MDF150A50          | NE57810S/N1         | PDTD123TK       | PEB2086HV1.1        |
| RF505TF6S            | S-8051ANR-NB-Y5-T1 | SBLB10L25           | SM8S15A-E3/2D   | SMBF1060LT1         |
| SPL03-10R            | SPX5205M5-L        | ST24W04M6TR         | TA2008-B        | TC4532BP            |
| TC554001FL-85V       | TPS2031DR          | V24B24E200BL        | D V48C3V3C50AL  | VI-26X-CY           |
| VI-BTL-EV            | VI-JW0-CW          | VLS201610HBX-2R2M-1 | W1068ND400      | ZTS30512            |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited