



 A Renesas Company	<b>ICL3232ECV-16Z-T7A</b>
	<b>Manufacturer Part Number:</b> ICL3232ECV-16Z-T7A
	<b>Manufacturer/Brand:</b> Intersil
	<b>Part of Description:</b> IC TXRX RS232 DUAL ESD 16TSSOP
	<b>Datasheets:</b>  <a href="#">ICL3232ECV-16Z-T7A.pdf</a>
	<b>RoHS Status:</b>  Lead free / RoHS
	<b>Stock Condition:</b> Compliant New original, Stock Available.
	<b>Ship From:</b> Hong Kong
	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS









### Specifications

Part Number	ICL3232ECV-16Z-T7A
Manufacturer	Intersil
Description	IC TXRX RS232 DUAL ESD 16TSSOP
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	16-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	16-TSSOP
Voltage - Supply	3 V ~ 5.5 V
Protocol	RS232
Number of Drivers/Receivers	2/2
Duplex	Full
Receiver Hysteresis	500mV
Data Rate	250kbps
Packaging	Original-Reel®

ICL3232ECV-16Z-T7A is New Original in Stock, Search ICL3232ECV-16Z-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ICL3232ECV-16Z-T7A Intersil with warrantied and confidence. RFQ ICL3232ECV-16Z-T7A : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>ICL3232ECV-16</b> Intersil IC 2DRVR/2RCVR RS232 3V 16-TSSOP	 <b>ICL3232ECV-20T</b> Intersil IC 2DRVR/2RCVR RS232 3V 20-TSSOP	 <b>ICL3232ECV-20ZT</b> Intersil IC 2DRVR/2RCVR RS232 3V 20-TSSOP	 <b>ICL3232ECV-20</b> Intersil IC 2DRVR/2RCVR RS232 3V 20-TSSOP
 <b>ICL3232ECV-16Z-T</b> Intersil IC 2DRVR/2RCVR RS232 3V 16-TSSOP	 <b>ICL3232ECV-16T</b> Intersil IC 2DRVR/2RCVR RS232 3V 16-TSSOP	 <b>ICL3232ECVZ-16Z-T</b> INTSIER ICL3232ECVZ-16Z-T INTSIER	 <b>ICL3232ECV-20Z</b> Intersil IC 2DRVR/2RCVR RS232 3V 20-TSSOP

### Hot Parts

More

- |                      |                 |                      |                   |                   |
|----------------------|-----------------|----------------------|-------------------|-------------------|
| ⊕ 08055A821KAT4A     | ↔ AOB12T60PL    | ⇒ AT30TS75A-SS8M-T   | D BT131-600       | ⇒ BTS611L1        |
| ⊕ BZX84-C33/DG/B2    | ⊕ C4D05120A     | D CL02B121KP2NNNC    | ⇒ CP2296GITLX     | ⇒ CS611816A       |
| ⊕ CSTCE16M8V53-R0    | ⊕ DD55N08L      | ⊕ DMS2085LSD-13      | ↔ EE-SX674A       | ⇒ FT250DM6        |
| D GQM1875C2E680JB12D | ⊕ HAL200-S      | ⊕ IDT7204L15J        | ⊕ IRF8707PBF      | ⇒ LE25FU206MA     |
| ⇒ LM431BIM3          | ↔ LT1013CP      | ⊕ M25P64-VMF6P       | ⊕ M29W160DT90N1   | ⇒ MA3X152EOL      |
| ↔ MAX1818EUT18       | ⇒ MIC29201-12WU | D NCP380HMU10AATBG   | ⊕ NE4211M01-T1-A  | ⊕ P01N02LMB       |
| ⊕ PCA8576FUG/2DA/QKP | D PHD66NQ03     | ⇒ R5F10267ASP        | ↔ RTC-4574NB      | ⇒ S-8211CAA-I6T1G |
| ⊕ SC2603ASKTRT       | ⊕ SFH5410-36-Z  | ↔ SI7110DN-T1-E3     | ⇒ SKFH150/08DT    | ⇒ SKKH57/06D      |
| ⊕ ST2G3236QTR        | ⊕ STB5NC50-1    | ⊕ SW06KBR935         | D SX8660I06YULTRT | ⇒ TC74VCX541FK    |
| ↔ TD210N11KOF        | ⊕ TP18Y6C2D-4   | ⊕ UQCSVA1R2BAT2A/500 | ⊕ XRT3588CN       | ⇒ Z86E0208PSC     |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited