





| | | |
|---|---|--|
|  | <h2 style="color: #E67E22;">MAX6865UK18D2L+T</h2> | |
| | Manufacturer Part Number: | MAX6865UK18D2L+T |
|  | Manufacturer/Brand: | Maxim Integrated |
| | Part of Description: | IC MPU SUPERVISOR SOT23-5 |
|  | Datasheets: | 1.MAX6865UK18D2L+T.pdf 2.MAX6865UK18D2L+T.pdf |
| | RoHs Status: |  Lead free / RoHS |
| Stock Condition: | Compliant New original, Stock Available. | |
| Ship From: | Hong Kong | |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS | |
| <p>Image may be representation. See specs for product details.</p> | | |

Specifications

| | |
|------------------------------|---|
| Part Number | MAX6865UK18D2L+T |
| Manufacturer | Maxim Integrated |
| Description | IC MPU SUPERVISOR SOT23-5 |
| Category | Integrated Circuits (ICs) > PMIC - Supervisors |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -40°C ~ 85°C (TA) |
| Mounting Type | Surface Mount |
| Type | Simple Reset/Power-On Reset |
| Package / Case | SC-74A, SOT-753 |
| Supplier Device Package | SOT-23-5 |
| Output | Push-Pull, Totem Pole |
| Reset | Active High |
| Number of Voltages Monitored | 1 |
| Reset Timeout | 40 ms Minimum |
| Voltage - Threshold | 1.8V |
| Packaging | Tape & Reel (TR) |

MAX6865UK18D2L+T is New Original in Stock, Search MAX6865UK18D2L+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6865UK18D2L+T Maxim Integrated with warrantied and confidence. RFQ MAX6865UK18D2L+T : Info@Y-IC.com

You May Be Also Be interested

| | | | |
|---|---|--|---|
| In:  <p>MAX6865UK17D5S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK18D4L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK18D3S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK18D1S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |
|  <p>MAX6865UK17D6S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK18D4S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK17D6L+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |  <p>MAX6865UK18D2S+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p> |

Hot Parts

[More](#)

| | | | | |
|--------------------------------------|------------------------------------|------------------------------------|-----------------------------------|---|
| 12065A4R7DAT2A | 1812JA560JAT1A | 70HFLR40S02 | AAT3113ITP-20-TI | AD9762AR+ |
| AGQ20006 | AP2171DFMG-7 | ASM812SEUS | BQ24045DSQT | CAT24FC32PI |
| CGA4J3X7R1H474K125AB | CM03X5R225M06AH | CY241V8ASXC-12 | DMG1013T | DT93N14LOF |
| FGH25N120FTDS | GRM0335C1H100JD01J | GRM31MR72A473MA01L | IRFPE30PBF | L20ESDL3V3C6-4 |
| LFE3-150EA-8FN1156I | LM3710XQMM-308NOPB | MAX793ESE | MCP1702T-1802E/CB | MT29F512G08CKECBH7-12:C |
| N450SH20 | PAL16R6ANC | PBSS2515E | PS9611L-E4 | RBR2LAM30ATF |
| RPM840-H11E2 | RT8207LGQW-QFN24 | SC111601VFU | SCH2808-S-TL-E | SI-3025KM-TL |
| SIHF8N50L | SKKL500/16E | SKY65206-11 | SRDA3.3-6.TBT | STW7N95K3 |
| SZMMSZ5248BT1G | T99N1400EOB | TC7WH241FU | TL7702BCP | UA741CDRG4 |
| UMK063CG5R6DT-F | V62/06626-07XE | VI-26Y-EV | XRP2526ID-2-F | XVO48F015M100 |

Contact us:Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited