 <p>A Renesas Company</p>	<p>X40030V14I-BT1</p>
	<p>Manufacturer Part Number: X40030V14I-BT1</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC VOLTAGE MONITOR TRPL 14-TSSOP</p> <p>Datasheets: X40030V14I-BT1.pdf</p> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <p>Stock Condition: New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	X40030V14I-BT1
Manufacturer	Intersil
Description	IC VOLTAGE MONITOR TRPL 14-TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Multi-Voltage Supervisor
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Push-Pull, Totem Pole
Reset	Active High
Number of Voltages Monitored	3
Reset Timeout	Adjustable/Selectable
Voltage - Threshold	1.8V, 2.6V, 4.4V
Packaging	Tape & Reel (TR)

X40030V14I-BT1 is New Original in Stock, Search X40030V14I-BT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X40030V14I-BT1 Intersil with warrantied and confidence. RFQ X40030V14I-BT1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X40030V14I-A Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40030V14I-B Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40031S14-B Intersil IC VOLTAGE MONITOR TRPL 14-SOIC</p>	 <p>X40031S14-AT1 Intersil IC VOLTAGE MONITOR TRPL 14-SOIC</p>
 <p>X40030V14I-AT1 Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40030V14I-CT1 Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40030V14I-C Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>	 <p>X40030V14-CT1 Intersil IC VOLTAGE MONITOR TRPL 14-TSSOP</p>

Hot Parts

[More](#)

- | | | | | |
|-----------------------------------|---------------------------------|------------------------------------|------------------------------------|-----------------------------------|
| 08055A681JAT2A | 302R29W151KV4E | 6DI75MA-060 | 6MBP15VSG060-50 | AR904P03 |
| C0603C0G1E6R2C | C0603X7R1A682K | CS0805KRX7RABB102 | DBLS107GRD | DD151N06K |
| DLLFSD01LPH4-7B | EXA20-48S3V3 | GJM0225C1E5R9CB01L | GRM43DR73A473KW01L | H11AG1TM |
| HMK212BBJ105KG-TE | ILQ615-2-X017 | IRF7413ZGTRPBF. | IRFS720B | KS823C04TB16L |
| LC75884WHS-QD-TLM | LD055A101JAB2A | MAX7624CPE+ | MC14584BF | MC74AC540DWG |
| MC74VHC00DR2 | MCC7216IO | MIC23031-AYMT | NFL18ST107X1C3D | NJM2886DL3-05-TE1 |
| NR4010T3R3M | NTP75N03RG | PCHMB100B12 | PRF18BD471QB2RB | RM20CA-12S |
| SC1186CSW | SET23A05L02 | SI-8120JD | SIR476DP-T1-E3 | T6100218 |
| T85HFL80S02 | TC2015-2.7VCTTR | TC74VCX573FT | TCST2103 | TP0620N3 |
| TS1005IG5T | TWL93017CZPHR | UCC3818NG4 | VI-810311 | XL180WCPZA-RL |