	<p>MP2487DN</p>
	<p>Manufacturer Part Number: MP2487DN</p> <p>Manufacturer/Brand: MPS</p> <p>Part of Description: MPS SOP-8</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 1400 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	




Specifications

Part Number	MP2487DN
Manufacturer	MPS
Description	MPS SOP-8
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	1400 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

MP2487DN is New Original in Stock, Search MP2487DN Datasheets, PDF, Inventory at Y-IC.com Online, Order MP2487DN with warrantied and confidence. RFQ MP2487DN : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MP2488DN-C449-LF-Z MPS MPS SOP8</p>	 <p>MP2483DS-LF MPS (Monolithic Power Systems) IC LED DRIVER</p>	 <p>MP2488DN MPS MPS SOP-8</p>	 <p>MP2487DN-LF-Z MPS MP2487DN-LF-Z MPS</p>
 <p>MP2488DN-LF MPS (Monolithic Power Systems) IC REG BUCK SYNC 55V 2A</p>	 <p>MP2483DS MPS MPS SOP-14</p>	 <p>MP24875DN-LF MPS (Monolithic Power Systems) IC REG BUCK SYNC 55V 1.5A</p>	 <p>MP2483DS-LF-Z MPS (Monolithic Power Systems) IC LED DRIVER</p>

Hot Parts

[More](#)

- | | | | | |
|----------------------|---------------------|-----------------------|------------------------|----------------------|
| ⊕ 5STF10F3080 | ↔ BAT46W-E3-08 | ⇒ BD3512MUV-E2 | D BL-HGB35A-TRB | ⇒ BU3081FV-GE2 |
| ⊖ BZT52C15T1G | ⊕ C0805C220J1GAC | D C2012C0G2E821K060AA | ⇒ CGA3E3X7S2A473K080AB | ⇒ CL05X105KQ5NNNC |
| ⊕ DS90CF562MTDX/NOPB | ⊖ FAN3224TU_F085 | ⊕ FDS8840NZ-NL | ↔ FDS9933BZ-NL | ⇒ GRM0336S1E3R4CD01D |
| D HFA04SD60S | ⊕ IL4118-X007T | ⊖ IMP708JESA | ⊕ INT5500A1G | ⇒ IR928-6C-F |
| ⇒ IRFZ24NPBF | ↔ L4931CDT40-TR | ⊕ LD035C271JAB2A | ⊖ LM75BIMMX-3 | ⇒ LMX2433TMC |
| ↔ LT1307BCMS8#TR | ⇒ MC100EPT21MNR4 | D MMF300YB070U | ⊕ MP8668DL-C223-LF-Z | ⊖ MSD306PT-LF-Z1-SB |
| ⊕ NCP382HD10AAR2G | D NL565050T-103J-PF | ⇒ PDS1040L-13 | ↔ PGA2500IDBRG4 | ⇒ PIC16LF1936T-I/SS |
| ⊖ PS20341-N | ⊕ RRL025P03FRA | ↔ S558-5500-12-F | ⇒ SAB-C1610-LM | ⇒ SFH9250L |
| ⊕ SMA5J14CA-E3/61 | ⊖ STD100NH02L-06 | ⊕ TC140G18AF-0068 | D TCR2LF18 | ⇒ UC232H02R5C-T |
| ↔ UCD9240RGCR | ⊕ V28A8C200BL | ⊖ WG15039SP | ⊕ Z0853006PSC | ⇒ ZAG2230-11S |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited