

	<h2 style="color: #D9534F;">ZL40205LDG1</h2>	
	Manufacturer Part Number:	ZL40205LDG1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFFER 1:6 750MHZ 32QFN
	Datasheets:	1.ZL40205LDG1.pdf 2.ZL40205LDG1.pdf 3.ZL40205LDG1.pdf
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	









Specifications

Part Number	ZL40205LDG1
Manufacturer	Microsemi
Description	IC CLK BUFFER 1:6 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	1:6
Differential - Input:Output	Yes/Yes
Packaging	Tray

ZL40205LDG1 is New Original in Stock, Search ZL40205LDG1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40205LDG1 Microsemi with warrantied and confidence. RFQ
 ZL40205LDG1 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>ZL40207LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40206LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40206LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40205LDF1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>
 <p>ZL40204LDF1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>	 <p>ZL40208LDF1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>	 <p>ZL40203LDG1 Microsemi IC CLK BUFFER 1:4 750MHZ 16QFN</p>	 <p>ZL40204LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>

Hot Parts More

- | | | | | |
|--------------------|----------------------------|-----------------------|-------------------------|-----------------------|
| ⚙️ 06033A331F4T4A | ➡️ 2-487951-6 | ➡️ 24AA08T-I/MNY | D 25LC160B-I/ST | ➡️ A3968SLB |
| ⚡ BL115-10RL-TAGF | ⚙️ C0805C102K1RAC | D CDRH3D16/LDNP-470NC | ➡️ CGA5L2X7R1E105K160AA | ➡️ CMLT3906ETR |
| ⚙️ DD200HB-160 | ⚡ EPM7064STC100-10 | ⚙️ FSBB20CH60SL | ➡️ GRM0225C1E7R3DDAEL | ➡️ GRM0335C1E4R5BD01D |
| D HD6435368TFW | ⚙️ L06031R5CGSTR | ⚡ LDC311G9610B-707 | ⚙️ LT1117CST-5.0 | ➡️ LTC3826IUH#TRPBF |
| ➡️ LTC6247CMS8#PBF | ➡️ MA3036-L | ⚙️ MD2100B-B | ⚡ MIC23150-4YMT | ➡️ NCV887601D1R2G |
| ➡️ NDD02N40 | ➡️ NRH3010T3R3MN/PH3R3AMT4 | D P202CH08 | ⚙️ PQ12SZ11 | ⚡ PS2581A-1 |
| ⚙️ PS9711-E3 | D RB083L-20 | ➡️ S-1339A18-A4T4U3 | ➡️ S-80747AN-JB-T1 | ➡️ S-80825ANY-B |
| ⚡ S-8261BAT-M6T1U | ⚙️ SF1000GX24 | ➡️ SF14-1960M5UBA1 | ➡️ SIP4282ADVP-3-E3 | ➡️ SMSZ1600-20T3 |
| ⚙️ SN74BCT125AN | ⚡ SOMC1601-103G | ⚙️ STM32F100R4T6B | D T560N14TOF | ➡️ TC7SET00FU |
| ➡️ THS7373IPW | ⚙️ TLC0838CDWR | ⚡ TLE2027CDR | ⚙️ UCC3585M | ➡️ ZXCT1022E5TA |