


	<p>IDT5T9890NLGI8</p>
	<p>Manufacturer Part Number: IDT5T9890NLGI8</p>
	<p>Manufacturer/Brand: IDT (Integrated Device Technology)</p>
	<p>Part of Description: IC CLK DRIVER 2.5V PLL 68-VFQFPN</p>
<p>Image may be representation. See specs for product details.</p>	<p>Datasheets:  IDT5T9890NLGI8.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>









Specifications

Part Number	IDT5T9890NLGI8
Manufacturer	IDT (Integrated Device Technology)
Description	IC CLK DRIVER 2.5V PLL 68-VFQFPN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	PLL Clock Driver
Frequency - Max	250MHz
Package / Case	68-VFQFN Exposed Pad
Supplier Device Package	68-VFQFPN (10x10)
Number of Circuits	1
Voltage - Supply	2.3 V ~ 2.7 V
Output	eHSTL, HSTL, LVTTTL
Input	eHSTL, HSTL, LVPECL, LVTTTL
PLL	Yes with Bypass
Ratio - Input:Output	2:10
Differential - Input:Output	Yes/No
Divider/Multiplier	Yes/No
Packaging	Tape & Reel (TR)

IDT5T9890NLGI8 is New Original in Stock, Search IDT5T9890NLGI8 Datasheets, PDF, Inventory at Y-IC.com Online, Order IDT5T9890NLGI8 IDT (Integrated Device Technology) with warrantied and confidence. RFQ IDT5T9890NLGI8 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>IDT5T9890NLGI IDT (Integrated Device Technology) IC CLK DRIVER 2.5V PLL 68-VFQFPN</p>	 <p>IDT5T9821NLI8 IDT (Integrated Device Technology) IC CLK DRIVER ZD PLL 68-VFQFPN</p>	 <p>IDT5T9891NLI IDT (Integrated Device Technology) IC CLK DRIVER 2.5V PLL 68-VFQFPN</p>	 <p>IDT5T9890NLI IDT (Integrated Device Technology) IC CLK DRIVER 2.5V PLL 68-VFQFPN</p>
 <p>IDT5T9891NLGI IDT (Integrated Device Technology) IC CLK DRIVER 2.5V PLL 68-VFQFPN</p>	 <p>IDT5T9821NLGI IDT (Integrated Device Technology) IC CLK DRIVER ZD PLL 68-VFQFPN</p>	 <p>IDT5T9821NLI IDT (Integrated Device Technology) IC CLK DRIVER ZD PLL 68-VFQFPN</p>	 <p>IDT5T9890NLI8 IDT (Integrated Device Technology) IC CLK DRIVER 2.5V PLL 68-VFQFPN</p>

Hot Parts

More

- | | | | | |
|-------------------------|-------------------|----------------------|------------------|------------------------|
| ⊛ 0603YC822JAZ2A | ↔ 08051A3R6CAT2M | ⇒ 08055A510JA2A | D 7MBR50VN120-50 | ↔ ACT4070YH-T |
| ⊣ AD628ARZ | ⊛ ADM6999X-A2-T-1 | D AN8013SH-E1 | ⇒ API-215-99719 | ↔ AT24C04BN-10SU-2.7 |
| ⊛ AT25040AN-10SE-2.7 | ⊣ AT707P11 | ⊛ BWR-5/700-D5AC | ↔ BZG05C3V9TR3 | ↔ CGA2B3X7R0J154M050BB |
| D CIL10J3R3KNC/1608-3R3 | ⊛ DCR1596SW47 | ⊣ FAN5646UC00X | ⊛ FDD107AN06LA0 | ↔ FP25R12W1T4 |
| ⇒ GRM21BR61A475KA73L | ↔ HD64F36077GHV | ⊛ HZD05-24T05P12P05I | ⊣ IR2011STRPBF | ↔ IXTP4N45 |
| ↔ LMBR280FT1G | ⇒ LT1054CS | D LT4320IMSE#PBF | ⊛ M0863LC340 | ⊣ MC56F8322VFAE |
| ⊛ MI-J2M-IA | D MIC5209-2.5WS | ⇒ MID400WV | ↔ NSM2104J425G3R | ↔ PESD3V31UB |
| ⊣ RGP10D-E3/73 | ⊛ RT9016-25PB | ↔ S-81250SGUP-DQD-T2 | ⇒ SKKH15/08 | ↔ SMAJ13A-E3/61 |
| ⊛ SNJ54AS574FK | ⊣ STM8AUDIOHAAY | ⊛ STPS3045CT | D T8132NLT | ↔ TAJB107K006R |
| ↔ TC1413NEOA | ⊛ TMK063CH090DP-F | ⊣ UMK105CG6R8CW-F | ⊛ XC612N2302MR | ↔ ZLP12840H2864G |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited