


	<h2 style="color: #E67E22;">MAX6866UK16D1L+T</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">MAX6866UK16D1L+T</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Maxim Integrated</a>
	<b>Part of Description:</b>	IC MPU SUPERVISOR SOT23-5
	<b>Datasheets:</b>	<a href="#">1.MAX6866UK16D1L+T.pdf</a> <a href="#">2.MAX6866UK16D1L+T.pdf</a>
	<b>RoHs Status:</b>	 Lead free / RoHS
<b>Stock Condition:</b>	Compliant New original, Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	<a href="#">MAX6866UK16D1L+T</a>
Manufacturer	<a href="#">Maxim Integrated</a>
Description	IC MPU SUPERVISOR SOT23-5
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	<a href="#">Require For Quote &amp; Check Stock</a>
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	10 ms Minimum
Voltage - Threshold	1.575V
Packaging	Tape & Reel (TR)

MAX6866UK16D1L+T is New Original in Stock, Search MAX6866UK16D1L+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6866UK16D1L+T Maxim Integrated with warrantied and confidence. RFQ MAX6866UK16D1L+T : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested

<b>In:</b>  <p><b>MAX6865UK46D5L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6866UK16D3L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK46D6S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK46D5S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>
 <p><b>MAX6865UK46D4S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6866UK18D3L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6866UK16D3S+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p><b>MAX6865UK46D6L+T</b> Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>

### Hot Parts

[More](#)

<a href="#">08055C152KAJ4A</a>	<a href="#">12107A331KAT2A</a>	<a href="#">5SDA07P3245</a>	<a href="#">D A50L-1-0175</a>	<a href="#">AD8682ARMZ</a>
<a href="#">ADN4692EBRZ</a>	<a href="#">APL5331KA-TRG</a>	<a href="#">D AT24C01A</a>	<a href="#">B39182B9402K610</a>	<a href="#">CGA5H2X8R2A683M115AD</a>
<a href="#">CGA5H4X7R2J102K115AA</a>	<a href="#">CPH3115-TL-H</a>	<a href="#">DCX69-25TA</a>	<a href="#">FCD900N60Z</a>	<a href="#">FI-X30HL</a>
<a href="#">D GAL20V8B-25QJ</a>	<a href="#">GR8841KG</a>	<a href="#">GRM0335C1E680JD01J</a>	<a href="#">GRM152C80G104KE19D</a>	<a href="#">H11D3.SD</a>
<a href="#">HC-SN100V4B15</a>	<a href="#">HCPL0700</a>	<a href="#">HT-170USD</a>	<a href="#">HVC317BTRU</a>	<a href="#">ICS950405AF</a>
<a href="#">IRFPG40PBF</a>	<a href="#">K1300E70</a>	<a href="#">LMC7101BIM5X/NOPB</a>	<a href="#">LTC3704EMS#TRPBF</a>	<a href="#">LTW-193ZDM5</a>
<a href="#">M28W160CT90N1T</a>	<a href="#">M5M51008AFP-70</a>	<a href="#">MIC37100-2.5WS</a>	<a href="#">MLF1608DR39KTA00</a>	<a href="#">MMZ1005S800AT000</a>
<a href="#">MPC8270VVQLDA</a>	<a href="#">OP215GSZ</a>	<a href="#">PSND150E/08</a>	<a href="#">PVN013LS</a>	<a href="#">S-1000N16-N4T1G</a>
<a href="#">SC1531ACS</a>	<a href="#">SI1905DL-T1-E3</a>	<a href="#">SI4804BDY-T1</a>	<a href="#">SMCJ36CA</a>	<a href="#">SY100EP14UK4</a>
<a href="#">T14M256A-8J</a>	<a href="#">T700123504BY</a>	<a href="#">UCC3813DTR-5</a>	<a href="#">UMK316BJ474KLHT</a>	<a href="#">VE-J33-EY</a>

Contact us:[Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited