

 A Renesas Company	<b>EL1507CL-T7</b>
	<b>Manufacturer Part Number:</b> <a href="#">EL1507CL-T7</a>
	<b>Manufacturer/Brand:</b> <a href="#">Intersil</a>
	<b>Part of Description:</b> IC LINE DRIVER ADSL 16-QFN
<b>Datasheets:</b>  <a href="#">EL1507CL-T7.pdf</a>	<b>RoHs Status:</b> Contains lead / RoHS non-compliant
<b>Stock Condition:</b> New original, Stock Available.	<b>Ship From:</b> Hong Kong
<b>Image may be representation. See specs for product details.</b>	<b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS









### Specifications

Part Number	EL1507CL-T7
Manufacturer	Intersil
Description	IC LINE DRIVER ADSL 16-QFN
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Driver
Package / Case	16-VQFN Exposed Pad
Supplier Device Package	16-QFN-EP (4x4)
Voltage - Supply	12V
Protocol	DSL
Number of Drivers/Receivers	1/0
Duplex	-
Data Rate	-
Packaging	Tape & Reel (TR)

EL1507CL-T7 is New Original in Stock, Search EL1507CL-T7 Datasheets, PDF, Inventory at Y-IC.com Online, Order EL1507CL-T7 Intersil with warrantied and confidence. RFQ EL1507CL-T7 : Info@Y-IC.com

### You May Be Also Be interested

In:

 <b>EL1506CREZ-T7</b> Intersil IC LINE DRVR DUAL ADSL 28-HTSSOP	 <b>EL1507CS</b> Intersil IC LINE DRIVER ADSL 16-SOIC	 <b>EL1507CSZ</b> Intersil IC LINE DRIVER ADSL 16-SOIC	 <b>EL1506CREZ</b> Intersil IC LINE DRVR DUAL ADSL 28-HTSSOP
 <b>EL1507CLZ</b> INTERSI EL1507CLZ INTERSI	 <b>EL1507CL-T13</b> Intersil IC LINE DRIVER ADSL 16-QFN	 <b>EL1506CREZ-T13</b> Intersil IC LINE DRVR DUAL ADSL 28-HTSSOP	 <b>EL1507CS-T7</b> Intersil IC LINE DRIVER ADSL 16-SOIC

### Hot Parts

More

- |                  |                      |                          |                   |                        |
|------------------|----------------------|--------------------------|-------------------|------------------------|
| ⊛ 06033A3R6CAT4A | ↔ 06035C392JAT4A     | ⇒ 1812WC471KAT9A         | D ADAM26P20TG     | ⇒ AP9563GJ-HF          |
| ⊣ BD8012FVJ-GE2  | ⊛ BSM300GA100D       | D CDBB160SLR-HF          | ⇒ CDBB180-G       | ⇒ CGA4F2X8R1E154K085AD |
| ⊛ ELM4558BB-S    | ⊣ GRM1556P1H9R7CZ01D | ⊛ GRM1885C1H9R1DZ01D     | ↔ HT85132798      | ⇒ IRLZ14PBF            |
| D ISL83491IB-T   | ⊛ IX4427NTR          | ⊣ LD1117S50TR            | ⊛ LM1117IMPX-5.0  | ⇒ LMZ14201HTZE/NOPB    |
| ⇒ LT1239CS       | ↔ LT1521CS8-5#PBF    | ⊛ LT3513EUHF#TRPBF       | ⊣ LTV-357D        | ⇒ MAX3100CPD+          |
| ↔ MIC2171BU      | ⇒ MIC2251YML         | D MT58L256L36FS-10       | ⊛ N310CH06LOO     | ⊣ N330SH20             |
| ⊛ NM24C04LM8     | D NUP8011MUTAG       | ⇒ P2500SBMCL             | ↔ PI3B3257Q       | ⇒ PMBD6100             |
| ⊣ REG1117FA-2.5  | ⊛ RF110-12           | ↔ RS4180AL               | ⇒ SBR140SL3-7     | ⇒ SKKD260/06           |
| ⊛ SM16PHN100     | ⊣ SS8550DBU          | ⊛ SST39VF1601-70-4I-B3KE | D STPS15H100CB-TR | ⇒ STS10N3LH5           |
| ↔ SUD70N02-04P   | ⊛ TK11360BMCL-G      | ⊣ TL431PUN               | ⊛ VI-251-EW       | ⇒ W5092ZD240           |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited