

	<h2 style="color: #E67E22;">ICL3243CB</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">ICL3243CB</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Intersil</a>
	<b>Part of Description:</b>	IC 3DRVR/5RCVR RS232 3V 28-SOIC
<b>Datasheets:</b>	 <a href="#">ICL3243CB.pdf</a>	
<b>RoHs Status:</b>	Contains lead / RoHS non-compliant	
<b>Stock Condition:</b>	New original, 700 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		









### Specifications

Part Number	ICL3243CB
Manufacturer	Intersil
Description	IC 3DRVR/5RCVR RS232 3V 28-SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	700 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	28-SOIC (0.295", 7.50mm Width)
Supplier Device Package	28-SOIC
Voltage - Supply	3 V ~ 5.5 V
Protocol	RS232
Number of Drivers/Receivers	3/5
Duplex	Full
Receiver Hysteresis	300mV
Data Rate	250kbps
Packaging	Tape & Reel (TR)

ICL3243CB is New Original in Stock, Search ICL3243CB Datasheets, PDF, Inventory at Y-IC.com Online, Order ICL3243CB Intersil with warrantied and confidence. RFQ ICL3243CB : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>ICL3243CBZ-T</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-SOIC</p>	 <p><b>ICL3242CB</b> INTERSI ICL3242CB INTERSI</p>	 <p><b>ICL3243CBZ</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-SOIC</p>	 <p><b>ICL3243CV</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-TSSOP</p>
 <p><b>ICL3243CV-T</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-TSSOP+</p>	 <p><b>ICL3243CAZ-T</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-SSOP</p>	 <p><b>ICL3243CB-T</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-SOIC</p>	 <p><b>ICL3243CAZ</b> Intersil IC 3DRVR/5RCVR RS232 3V 28-SSOP</p>

### Hot Parts

More

- |                         |                      |                   |                  |                     |
|-------------------------|----------------------|-------------------|------------------|---------------------|
| ⊛ 12065A121JAT4P        | ↔ 2DI75A-050         | ⇒ 5STP30H1601     | D AD9777BSVZ     | ⇒ AM29F010-120EC    |
| ⊣ APT77H60J             | ⊛ AZ1084T-3.3E1      | D AZ2940H-9.0TRG1 | ⇒ BCR141WE6327   | ⇒ BUK7608-55        |
| ⊛ BZX84B5V6LT1G         | ⊣ C1808N100J302T     | ⊛ CAT25C02I       | ↔ DG3001DB-T1-E1 | ⇒ DMP3025LK3-13     |
| D DSPIC33FJ16MC304-E/PT | ⊛ DTA143TKAT146      | ⊣ EXA40-24S1V8    | ⊛ FM27C512V45L   | ⇒ FP10R12NT3        |
| ⇒ FW250-TL-E            | ↔ GRM033R60J225ME15D | ⊛ IPB085N06LG     | ⊣ ISL6140CBZ     | ⇒ KSH117TM          |
| ↔ LP5996SD-3308/NOPB    | ⇒ LT1521IST-5.0      | D LTC4210-1CS6    | ⊛ MCR25JZHFX1001 | ⊣ MG300M1K1         |
| ⊛ MMD250F120X           | D P2300SAL           | ⇒ PC74HCT373T     | ↔ PS2532-1       | ⇒ PWB60A300         |
| ⊣ QM20DX-H              | ⊛ RA201625XX         | ↔ SA17A-E3/73     | ⇒ SFH615A-4X008T | ⇒ SIP4612BDVP-T1-E3 |
| ⊛ SKIIP942GB120-3DL     | ⊣ SM5S14AHE3/2D      | ⊛ STM32F100RBH6B  | D SY100ELT24ZG   | ⇒ TC74VHC541F       |
| ↔ TL074AIYDT            | ⊛ TLV2372IDGKRG4     | ⊣ UDZSTE-1716B    | ⊛ VI-2T0-MY      | ⇒ WL1271BYFVR-M     |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited