


	<h2 style="color: #E67E22;">S-80918CLNB-G6NT2U</h2>
	<p>Manufacturer Part Number: S-80918CLNB-G6NT2U</p> <hr/> <p>Manufacturer/Brand: SII Semiconductor Corporation</p> <hr/> <p>Part of Description: IC VOLT DETECTOR 1.8V SC-82AB</p> <hr/> <p>Datasheets:  S-80918CLNB-G6NT2U.pdf</p> <hr/> <p>RoHs Status:  Lead free / RoHS</p> <hr/> <p>Stock Condition: Compliant New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	S-80918CLNB-G6NT2U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 1.8V SC-82AB
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-809xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-82A, SOT-343
Supplier Device Package	SC-82AB
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	18 ms Minimum
Voltage - Threshold	1.8V
Packaging	Tape & Reel (TR)

S-80918CLNB-G6NT2U is New Original in Stock, Search S-80918CLNB-G6NT2U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80918CLNB-G6NT2U SII Semiconductor Corporation with warrantied and confidence. RFQ S-80918CLNB-G6NT2U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80918CLMC SEIKO SEIKO SOT-153SOT23-5</p>	 <p>S-80918CLPF-G6NTFU SII Semiconductor Corporation IC VOLT DETECTOR 1.8V SNT-4A</p>	 <p>S-80918CNMC SEIKO SEIKO SOT-153SO</p>	 <p>S-80918CNMC-G SEK SEK SOT25</p>
 <p>S-80918ANMP-DDF-T2 SEIKO S-80918ANMP-DDF-T2 SEIKO</p>	 <p>S-80918CLNB-G6NT2G SII Semiconductor Corporation IC VOLT DETECTOR 1.8V SC-82AB</p>	 <p>S-80918CNMC-G8BT2G SII S-80918CNMC-G8BT2G SII</p>	 <p>S-80918CLPF-G6NTFG SII Semiconductor Corporation IC VOLT DETECTOR 1.8V SNT-4A</p>

Hot Parts

More

- | | | | | |
|-----------------------|-----------------------|------------------------|------------------------|-----------------------|
| ⚙️ 13003-822 | ➡️ AD7705BNZ | ➡️ AD7775AJR-4 | D AK4636ECB-L | ➡️ ALZ21B21 |
| ⊖ BD340S_L2_00001 | ⚙️ BD46315G-TR | D BD6583MUJ-AE2 | ➡️ C1005C0G1H221K050BA | ➡️ CA3146M96 |
| ⚙️ CD4517BE | ⊖ CDBB3100-HF | ⚙️ CDMC6D28NP-R47MC | ➡️ DS1608C-474MLC | ➡️ EFCH1819TDV1 |
| D ELM7523CEA-S | ⚙️ FDMA908PZ | ⊖ FM34W02ULMT8X | ⚙️ GQM2195C2E111JB12D | ➡️ GRM0335C1H3R0BA01J |
| ➡️ GRM033C80J153ME01D | ➡️ GRM1555C1E1R5BA01D | ⚙️ GRM1885C2A9R7DZ01D | ⊖ ICS9279AF-03LFT | ➡️ IRF540PBF |
| ➡️ IRLR8503TR | ➡️ IXDN55N120AU1 | D KDS184-RTK | ⚙️ LB11861M-TLM-E | ⊖ LM2679SX-3.3 |
| ⚙️ LMD18201TP | D LT6204CGN#TRPBF | ➡️ LTC1198-2BCS8#TRPBF | ➡️ MAX236EWG | ➡️ MB1519PF-G-BND-ER |
| ⊖ MGA-71543 | ⚙️ MP8046DF-LF-Z | ➡️ NJU7772F33 | ➡️ P6KE75CA-E3/73 | ➡️ PKA2212P |
| ⚙️ SC156615M-1.8.TR | ⊖ SI7668ADP-T1-E3 | ⚙️ SL6609KGNPDS | D SP3243ECA | ➡️ TK55A10J1 |
| ➡️ TLC2652AI-8DR | ⚙️ TT162N16 | ⊖ UC3845AD1013TR | ⚙️ VI-271-IY | ➡️ W180-51GT |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited