

 <p>Not Actual Photo YIC International Co., Limited.</p>	<p><b>B78AD</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">B78AD</a></p> <p><b>Manufacturer/Brand:</b> B</p> <p><b>Part of Description:</b> B SOP8</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 14400 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications	
Part Number	B78AD
Manufacturer	B
Description	B SOP8
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	14400 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

B78AD is New Original in Stock, Search B78AD Datasheets, PDF, Inventory at Y-IC.com Online, Order B78AD with warrantied and confidence. RFQ B78AD : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>B78512A7854A3</b> EPCOS EPCOS SMD</p>	 <p><b>B7852/B39182-B7852-K410-S09</b> EPCOS EPCOS SMD</p>	 <p><b>B7852</b> EPCOS EPCOS SMD</p>	 <p><b>B78512A8213A3</b> EPCOS EPCOS SMD</p>
 <p><b>B78508B1555A003</b> EPCOS EPCOS B78508</p>	 <p><b>B7851</b> EPCOS EPCOS SMD</p>	 <p><b>B78504A8595A3</b> COILCRA COILCRA SMD</p>	 <p><b>B7852/B39182-B7852-K410</b> EPCOS EPCOS SMD</p>

Hot Parts

More

- |                     |                      |                    |                      |                     |
|---------------------|----------------------|--------------------|----------------------|---------------------|
| # 06035A120GAT9A    | ↔ 08051A681KAT2A     | ⇒ 1-292207-7       | D ACS724KMATR-65AB-T | ⇒ AMC3526HDMT       |
| ↳ ASM3P18S19BF-08SR | # AT90USB162-16MU    | D CN611416B        | ⇒ CR60-060R          | ⇒ CT3019F7A         |
| # CVS-04TB          | ↳ FFP08H60STU        | # FQA70N15         | ↔ GRM155R61C225KE11D | ⇒ IR204C-A          |
| D LD2985AM31R       | # LM2676SDX-ADJ      | ↳ LP3984IMFX-1.5   | # LT3082ETS8#TRMPBF  | ⇒ LT3420EMS-1#TRPBF |
| ⇒ LTC1016CS8        | ↔ M29F400BB90N6T     | # MAX15013AASA+T   | ↳ MAX488ESA+         | ⇒ MAX680CSA         |
| ↔ MBL150GS6N        | ⇒ MCP3004-I/ST       | D MP2004DJ-DD-LF-Z | # MX29F080MC-90G     | ↳ N1588NS240        |
| # NFL18SP307X1C3D   | D NJM2901V           | ⇒ NLC322522T-4R7K  | ↔ P87C51RC+4B        | ⇒ PH5030AL          |
| ↳ PI3B3384LE        | # PIC18F4321T-I/PT   | ↔ PK40FG-40        | ⇒ R3636EC16T         | ⇒ R920172000        |
| # R9G20209CJ00      | ↳ S-80834CLMC-B6TT2G | # SCAN92LV090VEHX  | D TLC1078IDRG4       | ⇒ TMG10E60FS        |
| ↔ TMP275AIDRG4      | # TQM7M5012          | ↳ TSA5526T         | # UA78L05CPK         | ⇒ VI-26X-IV         |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited