









 <p>A Renesas Company</p>	<h2 style="color: red;">X9261US24IT1</h2>	
	Manufacturer Part Number:	X9261US24IT1
	Manufacturer/Brand:	Intersil
	Part of Description:	IC XDCP DUAL 256TAP 50K 24-SOIC
Datasheets:	 X9261US24IT1.pdf	
RoHs Status:	Contains lead / RoHS non-compliant	
Stock Condition:	New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Specifications

Part Number	X9261US24IT1
Manufacturer	Intersil
Description	IC XDCP DUAL 256TAP 50K 24-SOIC
Category	Integrated Circuits (ICs) > Data Acquisition - Digital
Part Status	Require For Quote & Check Stock
Series	XDCP™
Operating Temperature	-40°C ~ 85°C
Features	Selectable Address
Interface	SPI
Configuration	Potentiometer
Tolerance	±20%
Package / Case	24-SOIC (0.295", 7.50mm Width)
Supplier Device Package	24-SOIC
Number of Circuits	2
Voltage - Supply	5V
Memory Type	Non-Volatile
Resistance (Ohms)	50k
Taper	Linear
Number of Taps	256
Temperature Coefficient (Typ)	±300 ppm/°C
Resistance - Wiper (Ohms) (Typ)	150 (Max)
Packaging	Tape & Reel (TR)

X9261US24IT1 is New Original in Stock, Search X9261US24IT1 Datasheets, PDF, Inventory at Y-IC.com Online, Order X9261US24IT1 Intersil with warrantied and confidence. RFQ X9261US24IT1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>X9261US24I-2.7 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>	 <p>X9261US24IZ-2.7T1 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>	 <p>X9261US24-2.7 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>	 <p>X9261US24T1 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>
 <p>X9261US24IZ-2.7 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>	 <p>X9261US24I-2.7T1 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>	 <p>X9261US24-2.7T1 Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>	 <p>X9261US24I Intersil IC XDCP DUAL 256TAP 50K 24-SOIC</p>

Hot Parts

[More](#)

⊕ 0402YC681KAT2A	↔ 12062C103JAT2A	⇒ 12064D476MAT2A	D 12065C823JAT2A	⇒ 123NQ80R
⊖ 24LC16BT/SN SOP8	⊕ 2MBI300U4D-120-54	D 5034710200	⇒ A180-WLA	⇒ AD1584CRTZ-REEL7
⊕ AD22100ARZ-RL	⊖ ADF4153BCPZ	⊕ AP1117E25L-13	↔ AP1506-T5L-U	⇒ B39458M1971M100
D BA5810FM	⊕ BD62011FS-E2	⊖ BTS6123B	⊕ C1608X7R1C334K080AC	⇒ C3216CH2E822J160AA
⇒ CPH6341-TL-E	↔ DDZ9701T-7	⊕ FP25R12YT3	⊖ GFF200E14	⇒ HSMS-381E-TR1G
↔ HUF76143S3ST	⇒ LB11851MC-BH	D LM431AIZ/LFT1	⊕ LT1461BCS8-2.5	⊖ LT3050EDDB-5#TRPBF
⊕ LT3959FE	D LTC4150CMS#TRPBF	⇒ MAX3013EGP	↔ MC78L05ACP	⇒ MT1389DE-EEAL
⊖ PSND150E/08	⊕ RN1112FT	↔ SER1360-272KLD	⇒ SG-310SCN57.98000	⇒ SP3222EEA-L/TR
⊕ SP485EEN-L/R	⊖ SR4M4012	⊕ ST7263BM1/NHNTR	D STM32F051C8U6	⇒ STMPS2272TTR
↔ UMK107BBJ225KA-T	⊕ VNQ5E050KTR-E	⊖ VS-12CWQ04FNHM3	⊕ W42C31-03GTR	⇒ ZL30406QGC

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited