

 <p>A Renesas Company</p>	<p>CS82C59AZ96</p>
	<p>Manufacturer Part Number: CS82C59AZ96</p> <p>Manufacturer/Brand: Intersil</p> <p>Part of Description: IC INTERRUPT CTRLR 8MHZ 28PLCC</p> <p>Datasheets: PDF CS82C59AZ96.pdf</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: Compliant New original, 367 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	CS82C59AZ96
Manufacturer	Intersil
Description	IC INTERRUPT CTRLR 8MHZ 28PLCC
Category	Integrated Circuits (ICs) > Interface - Specialized
Part Status	367 pcs Stock
Series	-
Mounting Type	Surface Mount
Interface	System Bus
Applications	-
Package / Case	28-LCC (J-Lead)
Supplier Device Package	28-PLCC (11.51x11.51)
Voltage - Supply	4.5 V ~ 5.5 V
Packaging	Original-Reel®

CS82C59AZ96 is New Original in Stock, Search CS82C59AZ96 Datasheets, PDF, Inventory at Y-IC.com Online, Order CS82C59AZ96 Intersil with warrantied and confidence. RFQ
CS82C59AZ96 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>CS82C59AZ Intersil IC INTERRUPT CONTROLLER 28-PLCC</p>	 <p>CS82C59A-1296 Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>	 <p>CS82C84 INTERSI CS82C84 INTERSI</p>	 <p>CS82C59A96 Intersil IC INTERRUPTER CMOS 8MHZ 28-PLCC</p>
 <p>CS82C59A-12Z96 Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>	 <p>CS82C84AZ96 Intersil IC CLOCK GENERATOR DVR 20-PLCC</p>	 <p>CS82C59A-12Z Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>	 <p>CS82C84AZ Intersil IC DRIVER CLOCK GENERATOR 20PLCC</p>

Hot Parts

More

- | | | | | |
|------------------------|----------------------------|-------------------|------------------------|-----------------------|
| ⊕ 06031C181MAT2A | ↔ 2SP0325V2A0-CM1800DY-34S | ⇒ AD53504-02 | D ADC121S101CIMFX/NOPB | ⇒ ADS8863IDRCR |
| ⊖ AP3706P-G1 | ⊕ AS1358-BTTT-25 | D AUIRLS3034 | ⇒ BAJ5CC0FP-E2 | ⇒ C1608C0G1H030C080AA |
| ⊕ CGA3E2NP02A332J080AA | ⊖ CL05C040CB5NNNC | ⊕ CNW11AV-2 | ↔ CS80C286-25 | ⇒ CX1206MKX7R9BB104 |
| D EPA8501A | ⊕ FJD5304DTF | ⊖ FSD176MRBTUDTU | ⊕ IPB100N04S4-H2 | ⇒ IRFR110PBF |
| ⇒ IRFR2908TRPBF | ↔ ISL22424WV14Z | ⊕ ISL6174IRZ | ⊖ LPS6235-683MEC | ⇒ LT1236AIS8 |
| ↔ LTC3548EDD#TRPBF | ⇒ LTE-1650 | D LTW-594VS-S1 | ⊕ MT46V32M16BN-5B | ⊖ N490DH22K00 |
| ⊕ NJM13404V-TE1 | D PS2561AL1-1-A | ⇒ SI3909DV-T1-GE3 | ↔ SM13CX174 | ⇒ SMBD1106 |
| ⊖ SPH252012H1R5MT | ⊕ SS8P5C-M3/86A | ↔ TC74HC153AP | ⇒ TDA8708/C2 | ⇒ TF202E5-TL |
| ⊕ TLE7236SE | ⊖ TPS2044D | ⊕ TPS40222DRPRG4 | D UC2901DWTR | ⇒ UNR91AAGOL |
| ↔ VI-26W-CY | ⊕ VI-JL-EY | ⊖ VT262BWFQR-ADJ | ⊕ XC6213B122NR | ⇒ XP1215-TX |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited