










 <p>A Renesas Company</p>	<p>ISL32459EIBZ-T7A</p>
	<p>Manufacturer Part Number: ISL32459EIBZ-T7A</p>
	<p>Manufacturer/Brand: Intersil</p>
	<p>Part of Description: IC TXRX RS422/RS485 8SOIC</p>
	<p>Datasheets:  ISL32459EIBZ-T7A.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	ISL32459EIBZ-T7A
Manufacturer	Intersil
Description	IC TXRX RS422/RS485 8SOIC
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Transceiver
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Voltage - Supply	3 V ~ 5.5 V
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Half
Receiver Hysteresis	30mV
Data Rate	20Mbps
Packaging	Original-Reel®

ISL32459EIBZ-T7A is New Original in Stock, Search ISL32459EIBZ-T7A Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL32459EIBZ-T7A Intersil with warrantied and confidence.
RFQ ISL32459EIBZ-T7A : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ISL32459EIBZ Intersil IC TXRX 60V OVP 20V RS485 8SOIC</p>	 <p>ISL3246 INTERSIL ISL3246 INTERSIL</p>	 <p>ISL3245ECAZ INTERSI INTERSI SSOP28</p>	 <p>ISL3245EIAZ INTERSIL ISL3245EIAZ INTERSIL</p>
 <p>ISL32458EIBZ-T7A Intersil IC TXRX RS422/RS485 8SOIC</p>	 <p>ISL32470EIBZ Intersil IC TXRX RS485 FAULT PROT 14SOIC</p>	 <p>ISL32458EIBZ Intersil IC TXRX 5V RS422/485 8SOIC</p>	 <p>ISL32470EIBZ-T Intersil IC TXRX RS485 FAULT PROT 14SOIC</p>

Hot Parts

More

- | | | | | |
|-------------------|-----------------------|----------------------|----------------------|----------------------|
| ⊛ 08051U390KAT2A | ↔ 08055C561MAT2A | ⇒ 1812SA561JAT1A | D 1MBI300JP-120 | ⇒ AD5110BCPZ80-1-RL7 |
| ⊣ AOU2N60A | ⊛ AP50T10GS-HF | D BD9479FV | ⇒ C0603JB1A223K030BC | ⇒ CAT809SEUR |
| ⊛ CM800E2U-24F | ⊣ CPH3104-TL | ⊛ DDTD123TC-7-F | ↔ DP7113PI-50 | ⇒ ECLAMP2515K.TCT |
| D FDS6692A-NL | ⊛ FDU044AN03L | ⊣ GRM31CR61E226KE15K | ⊛ ICL3241CV-T | ⇒ IMP809LEUR |
| ⇒ IRF6612TR | ↔ LM22675MRX-ADJ/NOPB | ⊛ LM81BIMTX-3/NOPB | ⊣ LNJ312G8JOMC | ⇒ LP3875EMP-1.8 |
| ↔ LQP18MN15NG00D | ⇒ LT1223CS8#TRPBF | D LT1910ES8#TRPBF | ⊛ LTC1149CS-5#PTR | ⊣ LTC6957IDD-3#PBF |
| ⊛ MA3XD1700L | D MAX3223MPWREP | ⇒ MAZL120H01SO | ↔ MBM100JS6AW | ⇒ MC74LCX32DTR2 |
| ⊣ MCC255-14IO1B | ⊛ MT9P017D00STC | ↔ PTH12010LAS | ⇒ R1446NS08E | ⇒ RF9808SR |
| ⊛ RL7520WT-R006-G | ⊣ S9S08DZ60F1MLH | ⊛ SC420AIMLTRT | D SKKD380/20 | ⇒ SM20CXC166 |
| ↔ SN74HC373ANSR | ⊛ STP141NF55 | ⊣ SUD19N20-90-T4-E3 | ⊛ TPS72101DBVRG4 | ⇒ VBO20-16A02 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.
Copyright © 2019 YIC International Co., Limited