


	<p>X5325S8Z-4.5A</p>
	<p>Manufacturer Part Number: X5325S8Z-4.5A</p>
	<p>Manufacturer/Brand: Intersil</p>
	<p>Part of Description: IC CPU SUPERV 32K EE 8-SOIC</p>
	<p>Datasheets:  X5325S8Z-4.5A.pdf</p>
	<p>RoHS Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	X5325S8Z-4.5A
Manufacturer	Intersil
Description	IC CPU SUPERV 32K EE 8-SOIC
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Output	Open Drain or Open Collector
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.63V
Packaging	Tube

X5325S8Z-4.5A is New Original in Stock, Search X5325S8Z-4.5A Datasheets, PDF, Inventory at Y-IC.com Online, Order X5325S8Z-4.5A Intersil with warrantied and confidence. RFQ X5325S8Z-4.5A : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>X5325S8Z-2.7 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5325S8Z-2.7T1 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5325S8ZT1 Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5325V XICOR X5325V XICOR</p>
 <p>X5325V14-2.7A Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5325S8Z Intersil IC CPU SUPERV 32K EE 8-SOIC</p>	 <p>X5325V14 Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p>X5325S8T1 Intersil IC SUPERVISOR CPU 32K EE 8-SOIC</p>

Hot Parts

[More](#)

- | | | | | |
|------------------|--------------------|----------------------|---------------------|-------------------|
| ⊛ 06035U430GAT2A | ↔ 08055A5R1DAT2A | ⇒ 160MT140KB | D ADSP-2191MBST-140 | ⇒ AT29LV040A-20TI |
| ⊣ B481E-2T | ⊛ BSR188FSC | D CM75E3Y-24G | ⇒ CS300-12IO3 | ⇒ DBS150A24 |
| ⊛ DD106N16K-A | ⊣ DT46N06KOF | ⊛ DW2F100N060 | ↔ EVK105RH3R6JW-F | ⇒ FDMC3300NZA |
| D FPF1504UCX | ⊛ GBPC2508W | ⊣ GQM1885C2A2R7BB01D | ⊛ IRFS4610PBF | ⇒ KBC1100L-PU |
| ⇒ LM158APT | ↔ LP2995MX/NOPB | ⊛ LT3844IFE#TRPBF | ⊣ LTC1444CS | ⇒ MAX3323EEEUE+T |
| ↔ MAX5460EXK+T | ⇒ N351VC450 | D NJM12902V | ⊛ NTMD5836NL | ⊣ PAP-11V-S |
| ⊛ PCF85116-3D | D SCD03012T-100M-N | ⇒ SI7856DP-TI-E3 | ↔ SN65LVDS2DBVR | ⇒ SSC3S241CA |
| ⊣ STK65020MK3-B | ⊛ SUD50N03-12P-E3 | ↔ TEA5777HN/N1 | ⇒ TPS2042BDGNR | ⇒ TPS2363PFBR |
| ⊛ TPS65630ARTGR | ⊣ TR/3216FF-750MA | ⊛ UPD70216HGF-16-3B9 | D VI-21L-IU | ⇒ VI-J3M-EZ |
| ↔ VLC6045T-2R2N | ⊛ VS-30BQ100TRPBF | ⊣ X9314WSIZ | ⊛ ZMG2206-11S | ⇒ ZXMP6A17DN8TC |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited