




| | |
|--|--|
|  <p>ANALOG DEVICES AHEAD OF WHAT'S POSSIBLE™</p> | <p>Manufacturer Part Number: ADM695SQ</p> |
| | <p>Manufacturer/Brand: ADI (Analog Devices, Inc.)</p> |
|  | <p>Part of Description: IC SUPERVISOR MPU 4.65V 16CDIP</p> |
| | <p>Datasheets:  ADM695SQ.pdf</p> |
| | <p>RoHs Status: Contains lead / RoHS non-compliant</p> |
| | <p>Stock Condition: New original, Stock Available.</p> |
| | <p>Ship From: Hong Kong</p> |
| <p>Image may be representation. See specs for product details.</p> | <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p> |









Specifications

| | |
|------------------------------|--|
| Part Number | ADM695SQ |
| Manufacturer | ADI (Analog Devices, Inc.) |
| Description | IC SUPERVISOR MPU 4.65V 16CDIP |
| Category | Integrated Circuits (ICs) > PMIC - Supervisors |
| Part Status | Require For Quote & Check Stock |
| Series | - |
| Operating Temperature | -55°C ~ 125°C (TA) |
| Mounting Type | Through Hole |
| Type | Battery Backup Circuit |
| Package / Case | 16-CDIP (0.300", 7.62mm) |
| Supplier Device Package | 16-CDIP |
| Output | Open Drain, Push-Pull |
| Reset | Active High/Active Low |
| Number of Voltages Monitored | 1 |
| Reset Timeout | 140 ms Minimum |
| Voltage - Threshold | 4.65V |
| Packaging | Tube |

ADM695SQ is New Original in Stock, Search ADM695SQ Datasheets, PDF, Inventory at Y-IC.com Online, Order ADM695SQ ADI (Analog Devices, Inc.) with warrantied and confidence. RFQ ADM695SQ : Info@Y-IC.com

You May Be Also Be interested

In:

| | | | |
|--|--|---|---|
|  <p>ADM695AR ADI (Analog Devices, Inc.) IC SUPER MPU 4.65 100MA 16SOIC</p> |  <p>ADM696ANZ ADI (Analog Devices, Inc.) IC SUPERVISOR MPU 16DIP</p> |  <p>ADM6966FH International Rectifier (Infineon Technologies) ADM6966FH INFINEON</p> |  <p>ADM696AR-REEL ADI (Analog Devices, Inc.) ADM696AR-REEL AD</p> |
|  <p>ADM696AN ADI (Analog Devices, Inc.) IC SUPERVISOR MPU 100MA 16DIP</p> |  <p>ADM695ANZ ADI (Analog Devices, Inc.) IC SUPER MPU 4.65 100MA 16DIP</p> |  <p>ADM695ARZ-REEL ADI (Analog Devices, Inc.) IC SUPERVISOR MPU 4.65V 16SOIC</p> |  <p>ADM695AR-REEL ADI (Analog Devices, Inc.) IC SUPERVISOR MPU 4.65V 16SOIC</p> |

Hot Parts

More

- | | | | | |
|--------------------|-----------------------|----------------------|------------------------|-----------------------|
| ⚙️ ADS7819U | ➡️ AL60A-048L-018F30L | ➡️ AP1506-50K5L | D ATAR862M-083-TNQ48 | ➡️ BD8224EFV-E2 |
| ⊖ BSC0925ND | ⚙️ BZX84-C5V6/B | D CAT6217-280TD-GT3 | ➡️ CL160808T-R27K-N | ➡️ CL21A106KOCLRNL |
| ⚙️ CS1G-E3/I | ⊖ CXA1551P. | ⚙️ CY62148ELL-45ZSXI | ➡️ D5RB881M5E1BH-Z | ➡️ DEA162690LT-1217A2 |
| D DF04M-E3/45 | ⚙️ DS2155G+TR | ⊖ DS8925MX | ⚙️ EFCH1960TDA1 | ➡️ EL8176FWZ-T7 |
| ➡️ FSAV450MTCX | ➡️ HCPL-354-060 | ⚙️ IMP708TCSA-T | ⊖ IRU3137CSTRPBF. | ➡️ JMK325C7107MM-T |
| ➡️ L78M05CDT-1 | ➡️ MAX543CPA+ | D MAX825REUK | ⚙️ MB84VA2002-10PB-G | ⊖ MC74AC32DR2G |
| ⚙️ MDL30-48S05 | D MIC2937A-12BU | ➡️ MP3301GJ-Z | ➡️ NCP1117LPST15T3G | ➡️ P0366WC08A |
| ⊖ PM50B3475M43 | ⚙️ PW138C-30L | ➡️ RL1632-6C-R010-FN | ➡️ S-8261ABLMD-G3LT2U | ➡️ SI3469DV-T1-E3 |
| ⚙️ SN65LVDS047PWR | ⊖ SS24-E3/52T | ⚙️ STM32F105RBT6 | D STMPS2151MTR | ➡️ STS9NF30L |
| ➡️ SZMMBZ5240BLT1G | ⚙️ UCC28516DWR | ⊖ UMK105CH100DW-F | ⚙️ UPD70F3376M2GCA-UEU | ➡️ VI-20B-TX |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited