



 <p>A Renesas Company</p>	<h2 style="color: #E67E22;">CS82C59AZ</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">CS82C59AZ</a>
	<b>Manufacturer/Brand:</b>	<a href="#">Intersil</a>
	<b>Part of Description:</b>	IC INTERRUPT CONTROLLER 28-PLCC
<b>Datasheets:</b>	 <a href="#">CS82C59AZ.pdf</a>	
<b>RoHs Status:</b>	 Lead free / RoHS	
<b>Stock Condition:</b>	Compliant New original, 109 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	CS82C59AZ
Manufacturer	Intersil
Description	IC INTERRUPT CONTROLLER 28-PLCC
Category	Integrated Circuits (ICs) > Interface - Specialized
Part Status	109 pcs Stock
Series	-
Mounting Type	Surface Mount
Interface	System Bus
Applications	-
Package / Case	28-LCC (J-Lead)
Supplier Device Package	28-PLCC (11.51x11.51)
Voltage - Supply	4.5 V ~ 5.5 V
Packaging	Tube

CS82C59AZ is New Original in Stock, Search CS82C59AZ Datasheets, PDF, Inventory at Y-IC.com Online, Order CS82C59AZ Intersil with warrantied and confidence. RFQ CS82C59AZ : Info@Y-IC.com

### You May Be Also Be interested

In:

 <p><b>CS82C84AZ96</b> Intersil IC CLOCK GENERATOR DVR 20-PLCC</p>	 <p><b>CS82C59A-12Z</b> Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>	 <p><b>CS82C59A96</b> Intersil IC INTERRUPTER CMOS 8MHZ 28-PLCC</p>	 <p><b>CS82C59A-1296</b> Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>
 <p><b>CS82C84</b> INTERSI CS82C84 INTERSI</p>	 <p><b>CS82C84A</b> Intersil IC CLOCK GEN 5V 25MHZ 20-PLCC</p>	 <p><b>CS82C84AZ</b> Intersil IC DRIVER CLOCK GENERATOR 20PLCC</p>	 <p><b>CS82C59A-12Z96</b> Intersil IC CTRL INTERRUPT 12.5MHZ 28PLCC</p>

### Hot Parts

More

- |  |   |   |  |   |
|--|---|---|--|---|
| <ul style="list-style-type: none"> <li>⊕ 12063C153KAT2A</li> <li>⊖ AK4634EN-L</li> <li>⊕ CMR1U-01TR13</li> <li>D FARM2H11</li> <li>⇒ K7N161831B-PC16</li> <li>⇒ LTC1733EMSE#TRPBF.</li> <li>⊕ N1200CH42</li> <li>⊖ SI4916DY</li> <li>⊕ SR215C392KAATR</li> <li>⇒ TT46N04LOF</li> </ul> | <ul style="list-style-type: none"> <li>⇒ 1SMB5930BT3G</li> <li>⊕ BZX84-C4V3/WB6</li> <li>⊖ CY23S05SC-1HT</li> <li>⊕ HUF76443P3</li> <li>⇒ LMC660AIMX/NOPB</li> <li>⇒ LTC1778AEGN</li> <li>D NJM7820DL1A-TE1</li> <li>⊕ SM18PCN144</li> <li>⊖ ST7066U-OB-B</li> <li>⊕ UC2843BDT</li> </ul> | <ul style="list-style-type: none"> <li>⇒ 2220SC473KAT1A</li> <li>D C1005X7R1H103K050BB</li> <li>⊕ CY7C1021CV33-15V</li> <li>⊖ HY5S5B2CLFP-6E-C</li> <li>⊕ LT1460BIN8-10</li> <li>D M51976FP</li> <li>⇒ PC48F4400P0TB0EE</li> <li>⇒ SMAJ15A-E3/61</li> <li>⊕ T178N400TOC</li> <li>⊖ UNR9215J0L+</li> </ul> | <ul style="list-style-type: none"> <li>D 6R6D50A-050BHX-01</li> <li>⇒ CAT6219-285TD-GT3</li> <li>⇒ DM74S04N</li> <li>⊕ ISL8700AIBZ-T</li> <li>⊖ LT3466EDD#TRPBF</li> <li>⊕ MC74VHCT125ADR2</li> <li>⇒ RS3DA-13-F</li> <li>⇒ SMAJ9.0A</li> <li>D TC54VN5402ECB713</li> <li>⊕ VI-260-95</li> </ul> | <ul style="list-style-type: none"> <li>⇒ ADG202AKP</li> <li>⇒ CGA5L2X8R2A154K160AD</li> <li>⇒ ER2004FCT</li> <li>⇒ K4B2G1646F-BYMA</li> <li>⇒ LT6350HDD#TRPBF</li> <li>⊖ MM3Z8V2C</li> <li>⇒ RT9501BPF</li> <li>⇒ SP1001-04JTG</li> <li>⇒ TPS79930DDDCRG4</li> <li>⇒ VI-J14-EY</li> </ul> |
|--|---|---|--|---|

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited