









 <p>A Renesas Company</p>	<p><b>X5323V14I</b></p>
	<p><b>Manufacturer Part Number:</b> X5323V14I</p> <hr/> <p><b>Manufacturer/Brand:</b> Intersil</p> <hr/> <p><b>Part of Description:</b> IC SUPERVISOR CPU 32K EE 14TSSOP</p> <hr/> <p><b>Datasheets:</b>  <a href="#">X5323V14I.pdf</a></p> <hr/> <p><b>RoHs Status:</b> Contains lead / RoHS non-compliant</p> <hr/> <p><b>Stock Condition:</b> New original, Stock Available.</p> <hr/> <p><b>Ship From:</b> Hong Kong</p> <hr/> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

### Specifications

Part Number	X5323V14I
Manufacturer	Intersil
Description	IC SUPERVISOR CPU 32K EE 14TSSOP
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	14-TSSOP (0.173", 4.40mm Width)
Supplier Device Package	14-TSSOP
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	4.38V
Packaging	Tube









































X5323V14I is New Original in Stock, Search X5323V14I Datasheets, PDF, Inventory at Y-IC.com Online, Order X5323V14I Intersil with warrantied and confidence. RFQ X5323V14I : Info@Y-IC.com

### You May Be Also Be interested

<p><b>In:</b></p>  <p><b>X5323V14I-2.7T1</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14I-4.5A</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14-2.7T1</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>
 <p><b>X5323V14-2.7A</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14-4.5A</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14-2.7</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>	 <p><b>X5323V14I-2.7A</b> Intersil IC SUPERVISOR CPU 32K EE 14TSSOP</p>

### Hot Parts

More

 12061A471FAT4M	 151RF120	 1612634-1	 AAT1154IAS-2.5-T1	 AD9767AST
 AST1300A1-GP	 AY0438-P	 BD50FC0WEFJ	 BSC205N10NS3G	 C2012X7T2W103M085AA
 CC1206KKX5R9BB106	 CDF75A-120	 CL10C220JB8NNND	 ELM9337AB-S	 FDD4243_F085
 ID300A-030	 IRF1405ZSTRL7PP	 IRGPH50M	 IRLM110ATF	 IS42S16800D-7BL
 ISL24837AIRZ-T13	 ISL28430CVZ	 ISL6612BIRZ	 LAN89530AMR-A	 LP0402N2442ANTR
 LTC2920-1IS5#TRM	 MAX1706EEE	 MBRD630LT4G	 MI-270-IX	 MTT18M12
 PIC16C62BT-04I/SO	 PS7241-2A	 PSB54/08	 SA1117H-1.2TR	 SI4947DY-T1
 SI7491DP-T1-GE3	 SKIIP82ANB15	 SKT490/12D	 SN74ALVC16835DGGR	 SPLB20D-240A-C
 ST333S06PFM1	 SUCS102412B	 SW16PCN012	 T195F12ESM	 TL431AILPM
 TL431AIZ-AP	 TS12001ITD1022T	 UMK432C106MM-T	 US1D-M3/61T	 XC9111D501MR

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited