
 A Renesas Company	ISL6614IB-T
	Manufacturer Part Number: ISL6614IB-T
	Manufacturer/Brand: Intersil
	Part of Description: IC DRIVER DUAL SYNC BUCK 14-SOIC
Datasheets: ISL6614IB-T.pdf	RoHs Status: Contains lead / RoHS non-compliant
Stock Condition: New original, Stock Available.	Ship From: Hong Kong
Image may be representation. See specs for product details.	Shipment Way: DHL/Fedex/TNT/UPS/EMS









Specifications

Part Number	ISL6614IB-T
Manufacturer	Intersil
Description	IC DRIVER DUAL SYNC BUCK 14-SOIC
Category	Integrated Circuits (ICs) > PMIC - Gate Drivers
Part Status	Require For Quote & Check Stock
Series	-
Input Type	Non-Inverting
Operating Temperature	-40°C ~ 125°C (TJ)
Mounting Type	Surface Mount
Package / Case	14-SOIC (0.154", 3.90mm Width)
Supplier Device Package	14-SOIC
Voltage - Supply	10.8 V ~ 13.2 V
Channel Type	Synchronous
Driven Configuration	Half-Bridge
Number of Drivers	4
Gate Type	N-Channel MOSFET
Logic Voltage - VIL, VIH	-
Current - Peak Output (Source, Sink)	1.25A, 2A
Rise / Fall Time (Typ)	26ns, 18ns
High Side Voltage - Max (Bootstrap)	36V
Packaging	Tape & Reel (TR)

ISL6614IB-T is New Original in Stock, Search ISL6614IB-T Datasheets, PDF, Inventory at Y-IC.com Online, Order ISL6614IB-T Intersil with warrantied and confidence. RFQ ISL6614IB-T : Info@Y-IC.com

You May Be Also Be interested

In:

 ISL6614IB Intersil IC DRIVER MOSF DUAL SYNC 14SOIC	 ISL6614IBZR5238 Intersil IC DRVR DUAL SYNC BUCK 14-SOIC	 ISL6614CRZAR5214 Intersil IC DRVR DUAL SYNC BUCK 16-QFN	 ISL6614CRZR5238 Intersil IC DRVR DUAL SYNC BUCK 16-QFN
 ISL6614CRZR5214 Intersil IC DRVR DUAL SYNC BUCK 16-QFN	 ISL6614IBZ Intersil IC DRIVER DUAL SYNC BUCK 14-SOIC	 ISL6614IBZ-TR5238 Intersil IC DRVR DUAL SYNC BUCK 14-SOIC	 ISL6614IBZ-T Intersil IC DRIVER DUAL SYNC BUCK 14-SOIC

Hot Parts

More

- | | | | | |
|--------------------|-----------------------|-------------------------|--------------------|-------------------------|
| ⚙️ 04023U0R5BAT2A | ➡️ 04025A1R2BAT2A | ➡️ 12101U151FAT2A | D 2225HA471MAT1A | ➡️ A76L-0300-0191 |
| ⚡ AD7998BRUZ-1 | ⚙️ AD8320ARP | D AT30TS75-SS8-T | ➡️ AT93C46D-SH-T | ➡️ AZ1117T-1.8E1 |
| ⚙️ BCW60ATA | ⚡ C1608X8R1H223K080AA | ⚙️ CGA2B2X8R1E103M050BE | ➡️ CY283310XCT | ➡️ EPM3064AT144-7N |
| D FDPF12N50NZ | ⚙️ GQM2195C2E560JB12D | ⚡ HA1630S01CMEL | ⚙️ IPS1041LPBF | ➡️ IRKC270-08 |
| ➡️ LMC7215IMX/NOPB | ➡️ LP2992AILD-5.0 | ⚙️ LT1019CN-10 | ⚡ LT3482EUD#PBF | ➡️ LTC2655CUF-L12#TRPBF |
| ➡️ MAC228A6TG | ➡️ MAX3485CSA+T | D MB8422-12LP | ⚙️ MCD162-18io8 | ⚡ MCP4822-E/SN |
| ⚙️ MCU0805-25B154T | D PS9303L2-AX | ➡️ S29GL128P11TFI02 | ➡️ S6B0715A01-05XO | ➡️ SA501255-2081 |
| ⚡ SFW24R-4STAE1LF | ⚙️ SN65175N | ➡️ SN74CBT1G125DCKT | ➡️ SN74LC32APWR | ➡️ SN74LS157NSR |
| ⚙️ SPP80N03S2L-06 | ⚡ SSA24-E3/61T | ⚙️ TLV320AIC10CPFB | D TOP5050UTB-A-6 | ➡️ TPA6205A1DRBR |
| ➡️ TPS54260DGQR | ⚙️ TSV6291AILT | ⚡ TSX9231ST | ⚙️ VE-2T0-CW | ➡️ VI-J03-MX |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited