


	<p>S-1009C17I-M5T1U</p>
	<p>Manufacturer Part Number: S-1009C17I-M5T1U</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR</p>
<p>Datasheets:  S-1009C17I-M5T1U.pdf</p>	<p>RoHs Status:  Lead free / RoHS</p>
<p>Stock Condition: Compliant New original, Stock Available.</p>	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-1009C17I-M5T1U
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-1009
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	1.7V
Packaging	Tape & Reel (TR)

S-1009C17I-M5T1U is New Original in Stock, Search S-1009C17I-M5T1U Datasheets, PDF, Inventory at Y-IC.com Online, Order S-1009C17I-M5T1U SII Semiconductor Corporation with warrantied and confidence. RFQ S-1009C17I-M5T1U : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-1009C15I-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C17I-N4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C16I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C16I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>
 <p>S-1009C18I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C19I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C18I-M5T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>	 <p>S-1009C17I-I4T1U SII Semiconductor Corporation IC VOLT DETECTOR</p>

Hot Parts

More

- | | | | | |
|------------------------|------------------------|------------------------|------------------------|----------------------|
| ⊕ 06035A621GAT2A | ↔ 06035C122KAT2A | ⇒ 0805CC682ZAT1A | D 0805YA1R0CAT2A | ⇒ 12101A472GAT2A |
| ⊖ 12102C224KAT2A | ⊕ 1210AC103MAT1A | D A8299SETTR-T | ⇒ ACM4532F2NV-220T02 | ⇒ AF2-5.00V125TM |
| ⊕ BZA956AVL | ⊖ CC0402GRNPO9BN300 | ⊕ DMN32D2LFB4-7 | ↔ DS1553-100 | ⇒ ESMT729-M325 |
| D GRM31CB30J226ME18L | ⊕ GT-64120-B-4 | ⊖ HGTG7N60A4D | ⊕ IRF7701TR | ⇒ IS61LV25616AL-10KI |
| ⇒ JR31-60A | ↔ LM2841XMK-ADJL | ⊕ LTC1735CS#TRPBF | ⊖ LTC2921CGN-3.3#TRPBF | ⇒ LTC3207EUF-1#TRPBF |
| ↔ LTV-817S1-TP-B-G | ⇒ MB3775PFV-G-BND-ERE1 | D MBM29F002BC-70PD-SFK | ⊕ MC34071AP | ⊖ MCP4661T-104E/ST |
| ⊕ MCP6042-E/MS | D MG8Q6ES1 | ⇒ MP1580HS | ↔ N1600CH12KOO | ⇒ NRF52840-QIAA |
| ⊖ P100RH06CHO | ⊕ PS7212-1A-E4 | ↔ PS9317L-E3-AX | ⇒ RPC1S101-J | ⇒ SAI01-V1 |
| ⊕ SBR3045CT-G | ⊖ SI1035X-T1-GE3 | ⊕ TFDU6103-TT3 | D TL4050A50IDBZR | ⇒ TS2596CZ533 |
| ↔ TSL1315RA-221K1R7-PF | ⊕ V375B15C300BL2 | ⊖ V48B24T250BL3 | ⊕ VI-201-08 | ⇒ XC6221B10AMR-G |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited