



Not Actual Photo  
YIC International Co., Limited.

**CXK5V81000ATM-15LLB**

Manufacturer Part Number:	CXK5V81000ATM-15LLB
Manufacturer/Brand:	SONY
Part of Description:	SONY TSSOP
RoHs Status:	
Stock Condition:	New original, 2000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

Image may be representation.  
See specs for product details.

Specifications	
Part Number	CXK5V81000ATM-15LLB
Manufacturer	SONY
Description	SONY TSSOP
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	2000 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

CXK5V81000ATM-15LLB is New Original in Stock, Search CXK5V81000ATM-15LLB Datasheets, PDF, Inventory at Y-IC.com Online, Order CXK5V81000ATM-15LLB with warrantied and confidence. RFQ CXK5V81000ATM-15LLB : Info@Y-IC.com

You May Be Also Be interested

In:



Not Actual Photo  
YIC International Co., Limited.

**CXK5T16100TM-10**  
SONY



Not Actual Photo  
YIC International Co., Limited.

**CXK5972J-15**  
SONY  
SONY SOJ



Not Actual Photo  
YIC International Co., Limited.

**CXK5972P-15**  
SONY  
SONY DIP-28



Not Actual Photo  
YIC International Co., Limited.

**CXK5V8258J-20**  
SONY  
SONY SOJ/28



Not Actual Photo  
YIC International Co., Limited.

**CXK5T16100TM-12LLXTL**  
SONY  
SONY TSOP



Not Actual Photo  
YIC International Co., Limited.

**CXK5V8258TM-17**  
SONY  
SONY SOP32



Not Actual Photo  
YIC International Co., Limited.

**CXK7701J-35**  
SONY  
SONY PLCC



Not Actual Photo  
YIC International Co., Limited.

**CXK5T8257BM-12LLX**  
SONY  
SONY SOP

Hot Parts

More

⚙ 06031A750GAT4A

⚡ AD558JNZ

⚙ B32673P4225K

D CW100505-56NJ

➡ HCPL-817C

⚡ KDZTR12B

⚙ MAX134CMH

⚡ P1014AP06

⚙ SDIN9DS2-8G-Q

⚡ UPD485505GU-25-E2

⚡ 06031A820JAT7A

⚙ AD7266BCPZ

⚡ BD135-16

⚙ DS1000Z-100

⚡ HGTG40N60B3

➡ KSSGJ5D26

D MM74HC174MX

⚙ PE-68627NL

⚡ SN74HC05D

⚙ V48C2V2C66A3

➡ 06035A100D4T2A

D AD7873BRQZ

⚙ BD2244G-M

⚡ DS1107SG37

⚙ IPW50R399CP

D LMV932IDR

➡ MMBT3946DW1T1G

⚡ PSMN015-60PS

⚙ TCJH157M006R0200

⚡ VE-J34-CW

D 12065C391JAT2A

➡ AM4407M8R

⚡ CDBFN140-HF

⚙ GAL16V8D

⚡ IRF4905STRLPBF

⚙ LT1640LVCS8

⚡ MP8715DN-LF-Z

➡ RK73K1HTP39R

D TS27M2ID

⚙ VI-27Z-MY

➡ 12065C822KAT2A

➡ AP9566GH

➡ CDRH4D18NP-220NB

➡ GRM1555C1H131JA01D

➡ KD70F-40

⚡ LW010F81

➡ MP8768DL-LF-Z

➡ SA1630BE

➡ UMK105CG820KV-F

➡ VUI30-12N01

Contact us:**Info@Y-IC.com**

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited