

 <p>Not Actual Photo YIC International Co., Limited.</p>	<p><b>ME4825-G</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">ME4825-G</a></p> <p><b>Manufacturer/Brand:</b> Matsuki</p> <p><b>Part of Description:</b> Matsuki SOP-8</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 12700 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

**Specifications**

Part Number	ME4825-G
Manufacturer	Matsuki
Description	Matsuki SOP-8
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	12700 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

ME4825-G is New Original in Stock, Search ME4825-G Datasheets, PDF, Inventory at Y-IC.com Online, Order ME4825-G with warrantied and confidence. RFQ ME4825-G : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>ME4812A</b> Original SOP-8</p>	 <p><b>ME4812A-G</b> Matsuki Matsuki SOP-8</p>	 <p><b>ME4856</b> MATSUKI MATSUKI SOP</p>	 <p><b>ME4840</b> Matsuki Matsuki SOP-8</p>
 <p><b>ME4825</b> Original SOP-8</p>	 <p><b>ME4812B</b> M M SOP-8</p>	 <p><b>ME4835.</b> ME ME SOIC-8</p>	 <p><b>ME4812B-G</b> Matsuki Matsuki SOP-8</p>

Hot Parts

[More](#)

- |                          |                       |                      |                    |                        |
|--------------------------|-----------------------|----------------------|--------------------|------------------------|
| ⊕ 02016C472KAT2A         | ↔ 18123A393JAT2A      | ⇒ 2220AC104KAT1A     | D A52HA7.5A-C      | ⇒ AM27C040-150JC       |
| ⊖ AT24C04-10TU-2.7       | ⊕ BS120E0F            | D BZM55C24-TR        | ⇒ C1608CB-68NJ     | ⇒ CGA8N3X7R2E474M230KA |
| ⊕ CM50AD-12H             | ⊖ DS1233DZ-5          | ⊕ DTC144WKT147       | ↔ ERDS2TJ202T      | ⇒ FM24C128A-SO-U-G     |
| D FYFP1010DNTV           | ⊕ GRM188R61A106ME69D  | ⊖ GRM2195C2A150JZ01D | ⊕ HD6432215BK15TEV | ⇒ IRLM110ATF-NL        |
| ⇒ IRU1117-18CSTR         | ↔ LES15A48-5V0RE      | ⊕ LM4140CCMX-1.2     | ⊖ LT6205HS5#TRPBF. | ⇒ LTC6244HMS8          |
| ↔ LTC6655BHMS8-2.5#TRPBF | ⇒ LTC6905CSS-80#TRPBF | D MAX1284BESA+       | ⊕ MJE15035G        | ⊖ MMBT3906TT1          |
| ⊕ OPA2364A               | D P6KE16A-E3/73       | ⇒ PZH7M440           | ↔ RK73H1ETTP2702F  | ⇒ RNA52A10MMEL-E       |
| ⊖ SD700C40L              | ⊕ SI-3048LSA-TL       | ↔ SMA6F16A-M3/6A     | ⇒ SP207BEA         | ⇒ ST1284-01A8RL        |
| ⊕ STK621-320M            | ⊖ SUD40N08-16_08      | ⊕ SUD50N04-37P       | D TLV171IDR        | ⇒ TPS73133DBVRG4       |
| ↔ TS5A23167DCUR          | ⊕ UM1511-01WH         | ⊖ UMK325LD105KN-T    | ⊕ UPA1728G-E1-A    | ⇒ XC6228D252VR-G       |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited