 <p>Not Actual Photo YIC International Co., Limited.</p>	<p><b>2SJ287</b></p>
	<p><b>Manufacturer Part Number:</b> 2SJ287</p> <p><b>Manufacturer/Brand:</b> O</p> <p><b>Part of Description:</b> O SOT-89</p> <p><b>RoHs Status:</b></p> <p><b>Stock Condition:</b> New original, 41500 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	


**Specifications**

Part Number	2SJ287
Manufacturer	O
Description	O SOT-89
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	41500 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

2SJ287 is New Original in Stock, Search 2SJ287 Datasheets, PDF, Inventory at Y-IC.com Online, Order 2SJ287 with warrantied and confidence. RFQ 2SJ287 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p><b>2SJ287-TD</b> SANYO SANYO SOT89</p>	 <p><b>2SJ289</b> SANYO SANYO SOT-89</p>	 <p><b>2SJ288</b> O O SOT-89</p>	 <p><b>2SJ284</b> ON ON SOT-23</p>
 <p><b>2SJ284-TA</b> SANYO SANYO SOT-23</p>	 <p><b>2SJ285</b> SAYNO SAYNO SOT23</p>	 <p><b>2SJ285-TB</b> SANYO 2SJ285-TB SANYO</p>	 <p><b>2SJ288-TD</b> SANYO SANYO SOT89</p>

Hot Parts

More

- |                      |                      |                       |                  |                      |
|----------------------|----------------------|-----------------------|------------------|----------------------|
| ⊛ 08051C103M4T2A     | ↔ 18122A332JAT2A     | ⇒ 2MBI300-060         | D 70HFL160S02    | ⇒ BQ20Z75BTR         |
| ↳ BUK9511-55A        | ⊛ CC0402KRX7R9BB202  | D CPC1317P            | ⇒ CS3524AN       | ⇒ CTT60-08           |
| ⊛ DF13-2P-1.25DSA    | ↳ DTC144VU           | ⊛ EL5373IU            | ↔ FDMF6704       | ⇒ GLCR2012T100M-HC   |
| D GRM1557U1H6R7DZ01D | ⊛ GRM3195C2A182JA01D | ↳ HCNW137-000E        | ⊛ HEDS-9700-C51  | ⇒ HGTP7NA60A4D       |
| ⇒ IRKT170/08         | ↔ ISL9520HRTZ        | ⊛ LFB212G45CQ2D570    | ↳ LM4855LQ       | ⇒ LM99-1CIMMX        |
| ↔ LMX2335UTM         | ⇒ M0433WC140         | D MAX3395EETC+T       | ⊛ MF-SM050-2-99  | ↳ MRA4003T3          |
| ⊛ NJM2377V           | D P6KE130A           | ⇒ PIC24HJ64GP510-I/PF | ↔ PVG5A502C01R00 | ⇒ R9G01612           |
| ↳ RP109L151D-TR-FF   | ⊛ RT9193-36PB        | ↔ S-1170B15UC-OTATFG  | ⇒ SC4624MLTRT    | ⇒ SG2004-XS/TR       |
| ⊛ SI3457BDV-T1       | ↳ SN74HC138NSR       | ⊛ ST200S12POV         | D TEA19162T/2    | ⇒ TMOV14R275EPX2662  |
| ↔ TPS22933ARSER      | ⊛ VI-22L-MX          | ↳ VI-911310           | ⊛ VI-J13-CW-01   | ⇒ VS-STPS1045BTRR-M3 |