

	<p><b>X5163S8Z-2.7</b></p>
	<p><b>Manufacturer Part Number:</b> <a href="#">X5163S8Z-2.7</a></p> <p><b>Manufacturer/Brand:</b> <a href="#">Intersil</a></p> <p><b>Part of Description:</b> IC CPU SUPERV 16K EEPROM 8-SOIC</p> <p><b>Datasheets:</b>  <a href="#">X5163S8Z-2.7.pdf</a></p> <p><b>RoHS Status:</b>  Lead free / RoHS</p> <p><b>Stock Condition:</b> Compliant New original, 232 pcs Stock Available.</p> <p><b>Ship From:</b> Hong Kong</p> <p><b>Shipment Way:</b> DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	







### Specifications

Part Number	<a href="#">X5163S8Z-2.7</a>
Manufacturer	<a href="#">Intersil</a>
Description	IC CPU SUPERV 16K EEPROM 8-SOIC
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Supervisors</a>
Part Status	232 pcs Stock
Series	-
Operating Temperature	0°C ~ 70°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	100 ms Minimum
Voltage - Threshold	2.63V
Packaging	Tube

X5163S8Z-2.7 is New Original in Stock, Search X5163S8Z-2.7 Datasheets, PDF, Inventory at Y-IC.com Online, Order X5163S8Z-2.7 Intersil with warrantied and confidence. RFQ X5163S8Z-2.7 : [Info@Y-IC.com](mailto:Info@Y-IC.com)


































### You May Be Also Be interested

In:

 <p><b>X5163S8Z-2.7A</b> Intersil IC CPU SUPERV 16K EEPROM 8-SOIC</p>	 <p><b>X5163S8Z-4.5AT1</b> INTERSI X5163S8Z-4.5AT1 INTERSI</p>	 <p><b>X5163S8Z-2.7T1</b> Intersil IC CPU SUPERV 16K EEPROM 8-SOIC</p>	 <p><b>X5163S8IZ-4.5A</b> Intersil IC CPU SUPERV 16K EEPROM 8-SOIC</p>
 <p><b>X5163S8Z-4.5A</b> Intersil IC CPU SUPERV 16K EEPROM 8-SOIC</p>	 <p><b>X5163S8Z-2.7AT1</b> Intersil IC CPU SUPERV 16K EEPROM 8-SOIC</p>	 <p><b>X5163S8Z</b> Intersil IC CPU SUPERV 16K EEPROM 8-SOIC</p>	 <p><b>X5163S8T2</b> Intersil IC SUPERVISOR CPU 16K EE 8-SOIC</p>

### Hot Parts

[More](#)

- |  |   |  |   |   |
|--|---|--|---|---|
|  0402ZC393KAT2A   |  12065C272JAT4A      |  1565158-1        |  D ACPM-7500-TR1G |  AD80148BBCZRL |
|  ADS1251U         |  AP4409GEM           |  D AS1117-ADCX    |  BCM4329HKUBG     |  BCM56229B0KPB |
|  BD63222NUX-E2    |  C3216X7R1E684M/0.85 |  CL-196YG-CD-T    |  CL10C2R2CC81PNC  |  DS1631U+T     |
|  D DZ2J027M0L     |  FM25L256-G          |  FST30040         |  HFA3624IA1K      |  IRFU214PBF    |
|  IRG4RC10UDTR     |  IXTY18P10T          |  KSZ8851SNLI-TR   |  LE79R701QC       |  LL4448-GS18   |
|  LT1970ACFE#TRPBF |  LTV-702VS-TA1       |  D MBRF20100CTP   |  MM74C32N         |  MM74HCT374SJK |
|  MP1048EY         |  D MW6IC1940NB       |  PTVS64VS1UTR     |  R9G01018         |  RT9261-27GX   |
|  SFH615A-1        |  SMBJ26CA-E3/52      |  SN74HC4852QPWRQ1 |  SN761678BDCHR    |  STD5NK40ZT4   |
|  SZBZX84C10ET1G   |  TA75393FG           |  TB6581HG         |  D TL7715ACP      |  TPS53125PWR   |
|  TS117PLS         |  TV06B600J-HF        |  VI-J52-EW/F2     |  VIPER06LN        |  W0735SB04     |

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited