


	<h2 style="color: red;">S-80848CLPF-B69TFG</h2>
	<p>Manufacturer Part Number: S-80848CLPF-B69TFG</p> <hr/> <p>Manufacturer/Brand: SII Semiconductor Corporation</p> <hr/> <p>Part of Description: IC VOLT DETECTOR 4.8V SNT-4A</p> <hr/> <p>Datasheets:  S-80848CLPF-B69TFG.pdf</p> <hr/> <p>RoHS Status:  Lead free / RoHS</p> <hr/> <p>Stock Condition: Compliant New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	S-80848CLPF-B69TFG
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 4.8V SNT-4A
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	4-SMD, Flat Leads
Supplier Device Package	SNT-4A
Output	Push-Pull, Totem Pole
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	4.8V
Packaging	Tape & Reel (TR)

S-80848CLPF-B69TFG is New Original in Stock, Search S-80848CLPF-B69TFG Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80848CLPF-B69TFG SII Semiconductor Corporation with warrantied and confidence. RFQ S-80848CLPF-B69TFG : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80848CLMC-B69T2G SII Semiconductor Corporation IC VOLT DETECTOR 4.8V SOT23-5</p>	 <p>S-80848CLUA-B69T2U SII Semiconductor Corporation IC VOLT DETECTOR 4.8V SOT89-3</p>	 <p>S-80848CLUA-B69-T2 SEIKO SEIKO SOT-89</p>	 <p>S-80848CLNB-B69T2U SII Semiconductor Corporation IC VOLT DETECTOR 4.8V SC-82AB</p>
 <p>S-80848ANUP-EJC-T2 SEIKO SEIKO SOT89</p>	 <p>S-80848CLUA-B69T2G SII Semiconductor Corporation IC VOLT DETECTOR 4.8V SOT89-3</p>	 <p>S-80848CLPF-B69TFU SII Semiconductor Corporation IC VOLT DETECTOR 4.8V SNT-4A</p>	 <p>S-80848CLMC-B69T2U SII Semiconductor Corporation IC VOLT DETECTOR 4.8V SOT23-5</p>

Hot Parts

More

- | | | | | |
|----------------------|--------------------|---------------------|--------------------|--------------------|
| 06033C273KAT4A | 12067A1R5CAT2A | 1SMA51AT3G | D 74454168 | ACS722LLCTR-20AU-T |
| ADC1100-M | ADM810ZARTZ-REEL7 | D BCM4313KML1G-P20 | BGS110MC20-2 | BT139X-600E |
| BYM11-1000-E3/96 | BZY97C82 | C2012X7R2A103M085AE | CDRH4D18-3R3NC | CS300-16IO3 |
| D GCJ31CR72E473KXJ3L | GJM0335C1E2R9BB01D | GQM1875C2E4R3BB12D | GRM1556P1H4R8CZ01D | HD3SS215ZQER |
| IRGSL10B60KDPBF | ISL6217ACVZ-T | JW030B1-42M | K4B2G1646Q-BYK0 | KS221404 |
| LQW15AN62NG00D0X | LT1615ES5-1#TR | D LT1716IS5#TRPBF | M74VHC1GT08DFT1G | MAX3243EEAI+ |
| MBM29LV160TE90TN-CK | D MCP1725-1202E/MC | MIC5233-3.3YM5 | MJD45H11TF | MMBR911LT1 |
| PAH50S48-12/T | RM250UZ-M | S-80810CNNB-B90T2G | S9S08AW32E5WFGER | SKKH27/08 |
| SKT1200/12D | SMAJ20CA | SN74F125NSR | D SN75976A1DGG | SP508AEF-L |
| SPM0205HD4 | TMK063CG020DPGF | TPS61085PW | TPS71828-28YZCR | X9252WV24-2.7 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited