









	<h2 style="color: #E67E22;">ZL40205LDF1</h2>	
	Manufacturer Part Number:	ZL40205LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFFER 1:6 750MHZ 32QFN
	Datasheets:	1.ZL40205LDF1.pdf 2.ZL40205LDF1.pdf 3.ZL40205LDF1.pdf
Image may be representation. See specs for product details.	RoHS Status:	 Lead free / RoHS
	Stock Condition:	Compliant New original, Stock Available.
	Ship From:	Hong Kong
Shipment Way:		DHL/Fedex/TNT/UPS/EMS

Specifications

Part Number	ZL40205LDF1
Manufacturer	Microsemi
Description	IC CLK BUFFER 1:6 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	1:6
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40205LDF1 is New Original in Stock, Search ZL40205LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40205LDF1 Microsemi with warrantied and confidence. RFQ
ZL40205LDF1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ZL40207LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40206LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40205LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>	 <p>ZL40206LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>
 <p>ZL40207LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40204LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>	 <p>ZL40203LDF1 Microsemi IC CLK BUFFER 1:4 750MHZ 16QFN</p>	 <p>ZL40204LDF1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>

Hot Parts

More

- | | | | | |
|--------------------|------------------|-----------------------|-------------------|-------------------|
| # 04023A560KAT2A | ↔ 1206CA271JAT9A | ⇒ 7MBR20SA060D-01 | D AP2401B14KTR-G1 | ↔ APL5151-28BC-TR |
| ↳ AUIRS21811STRPBF | # BAT17-06E6327 | D BD9260FP-GE2 | ⇒ CDZT2R6.2B | ↔ CLH0603T-33NJ-F |
| # D2228N800 | ↳ DD231N18K | # DM74ALS11AMX | ↔ EMK212BJ155KD-T | ↔ FZ1200R33KF2C |
| D GA500TD60U | # HDC-300LT | ↳ IRFS654B | # IRMCK201. | ↔ ISL6268CAZ-T |
| ⇒ JMK325AC6107MM-T | ↔ LD2979M28TR | # LM2574DW-ADJR2 | ↳ LM3000ASQ/NOPB | ↔ LT1641IS8#PBF |
| ↔ LTW-482DS5 | ⇒ MBR10100 | D MIC2582-JYM | # MIC810MU | ↳ MMSZ4697ET1 |
| # NKT90/12A | D P0120CN5DA4 | ⇒ PAF400F280-1.8 | ↔ PIC12F510-I/MC | ↔ PS21205-E |
| ↳ QM100E3Y-24 | # RB095BM-30TL | ↔ RJK03M2DPA-00#J5A | ⇒ SD400C16C | ↔ SI3422DV |
| # SI4348DY | ↳ SML-P12DTT86 | # SN74ABT16240ADLR | D SRDA3.3-6.TB | ↔ STR755FR2T6 |
| ↔ TLZ13C-GS08 | # UPC2749T-E3 | ↳ UPD78F9418AGK-9EU-A | # WL1251BZQZR | ↔ WSL12064L000FEA |

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited