
	<p>PL502-05SC-R</p>
	<p>Manufacturer Part Number: PL502-05SC-R</p> <p>Manufacturer/Brand: Micrel / Microchip Technology</p> <p>Part of Description: IC VCXO 25MHZ 8SOIC</p> <p>RoHs Status:  Lead free / RoHS</p> <p>Stock Condition: ^{Compliant} New original, Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	PL502-05SC-R
Manufacturer	Micrel / Microchip Technology
Description	IC VCXO 25MHZ 8SOIC
Category	Integrated Circuits (ICs) > Clock/Timing - Clock
Part Status	Require For Quote & Check Stock
Series	*
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

PL502-05SC-R is New Original in Stock, Search PL502-05SC-R Datasheets, PDF, Inventory at Y-IC.com Online, Order PL502-05SC-R Micrel / Microchip Technology with warrantied and confidence. RFQ PL502-05SC-R : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>PL502-30DC Micrel / Microchip Technology IC VCXO</p>	 <p>PL502-04SC Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>	 <p>PL502-30WC Micrel / Microchip Technology IC VCXO</p>	 <p>PL502-110C Micrel / Microchip Technology IC VCXO 25MHZ 16TSSOP</p>
 <p>PL502-05SC Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>	 <p>PL502-110C-R Micrel / Microchip Technology IC VCXO 25MHZ 16TSSOP</p>	 <p>PL502-110CL PhaseLink PL502-110CL PhaseLink</p>	 <p>PL502-04SC-R Micrel / Microchip Technology IC VCXO 25MHZ 8SOIC</p>

Hot Parts

More

- | | | | | |
|---------------------|--------------------|-----------------------|--------------------------|---------------------|
| ⊛ 04025U8R8BAT2A | ↔ 12063A472KAT2A | ⇒ 1210GC332KAT1A | D 153PJA250 | ⇒ 2225HA101KAT1A\SB |
| ⊣ 23K256T-I/SN | ⊛ 2DI75ZA-100 | D ACE93C46FM+TH | ⇒ APS3628RS34P9 | ⇒ APT60M60JLL |
| ⊛ AT49SV322A-80CI-H | ⊣ BAT54AWPBF | ⊛ C3216X5R2A105K160AA | ↔ CC1206JRX7R9BB682 | ⇒ CIG22K2R2SDF |
| D CL05C680JB5NCNC | ⊛ CS13N50FA9R | ⊣ CS51414GDR8G | ⊛ CT0402V275RFG | ⇒ CY23S02SI-1T |
| ⇒ D050505D-1W | ↔ EMK316AB7475KLHT | ⊛ FBA50CC50 | ⊣ FQPF17N40T | ⇒ FS065C332KAZ2A |
| ↔ GT60N323 | ⇒ IL255-X007T | D IPD04N03LA | ⊛ IR3564BMPBF | ⊣ IXFT28N50F |
| ⊛ L-FW802C | D LM7808SX | ⇒ LP2904MX | ↔ LTC6655BHMS8-2.5#TRPBF | ⇒ LWD10-24D05 |
| ⊣ M157-YEB | ⊛ M30280FAHP | ↔ PIC18F4520-I/ML | ⇒ PL-2518B | ⇒ PN4117A_J61Z |
| ⊛ SiHF840S | ⊣ SKR3F20/08UNF | ⊛ SKY85318-11 | D SMCJ160A | ⇒ SPX2954AM3-L-5-0 |
| ↔ SSA250AA40 | ⊛ TIP31ATU | ⊣ TSM60N600CP | ⊛ V300C48H150B3 | ⇒ VNH3SP30TR-E |