


	<h2 style="color: #E67E22;">MAX6855UK29D2+T</h2>	
	Manufacturer Part Number:	MAX6855UK29D2+T
	Manufacturer/Brand:	Maxim Integrated
	Part of Description:	IC MPU SUPERVISOR SOT23-5
	Datasheets:	1.MAX6855UK29D2+T.pdf 2.MAX6855UK29D2+T.pdf
	RoHs Status:	 Lead free / RoHS
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	

Specifications

Part Number	MAX6855UK29D2+T
Manufacturer	Maxim Integrated
Description	IC MPU SUPERVISOR SOT23-5
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Simple Reset/Power-On Reset
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
Output	Push-Pull, Totem Pole
Reset	Active High
Number of Voltages Monitored	1
Reset Timeout	40 ms Minimum
Voltage - Threshold	2.925V
Packaging	Tape & Reel (TR)

MAX6855UK29D2+T is New Original in Stock, Search MAX6855UK29D2+T Datasheets, PDF, Inventory at Y-IC.com Online, Order MAX6855UK29D2+T Maxim Integrated with warrantied and confidence. RFQ MAX6855UK29D2+T : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>MAX6855UK29D4+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6855UK28D6+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6855UK29D5+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6855UK28D5+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>
 <p>MAX6855UK29D6+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6855UK29D3+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6855UK28D3+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>	 <p>MAX6855UK30D1+T Maxim Integrated IC MPU SUPERVISOR SOT23-5</p>

Hot Parts

[More](#)

- | | | | | |
|--|---|---|---|---|
| <ul style="list-style-type: none"> ⚙️ 1808AA300KAT1A ⚡ AP061CN3002MR ⚙️ ATMXT165-CCU D F4-25R12NS4 ⇒ IP-J10-CW ⇒ LM3424MHX ⚙️ MAX883ESA ⚡ POC-MP31ABB ⚙️ STP18NM60N ⇒ TT162N1600 | <ul style="list-style-type: none"> ⇒ ACPL-38JT-500E ⚙️ AP6982GM ⚡ BAS40-04T-7-F ⚙️ GRM033C80J393KE19D ⇒ LB3218T220M ⇒ LT1072CS D MCP2120-I/SL ⚙️ PT91-21B/RT7 ⚡ TDA3681JR ⚙️ TZX16B-TAP | <ul style="list-style-type: none"> ⇒ ADG408BN D AT42QT2160-MMU ⚙️ CGA7L1X7S3A222K160KA ⚡ HD6433980A62HV ⚙️ LCA210LSTR D LTC1596BCSW#TRPBF ⇒ MN101E31DKC ⇒ R2714ZC16H ⚙️ TDA5632M/C1 ⚡ UPD17241MC-367-5A4-E1 | <ul style="list-style-type: none"> D ADP3412JR-REEL ⇒ AT89C51RC2-RLTUM ⇒ DMN7022LFG-7 ⚙️ HGTP12N60A4 ⚡ LESDA5V3LT1G ⚙️ M0371YH350 ⇒ N520CH15 ⇒ SC1097D1 D TK17A65W ⚙️ V24C28C100A | <ul style="list-style-type: none"> ⇒ ADSP-2185MKST-300 ⇒ ATF-34143 ⇒ F1212S-2W ⇒ ICS9159M-14 ⇒ LM25088QMH-2 ⚡ M51953AF ⇒ P6SMB36CA ⇒ SCAN921023SLCX ⇒ TPS75915KTTR ⇒ V375B3V3T150AL |
|--|---|---|---|---|