
 <p>A Renesas Company</p>	<p>EL9110IU-T13</p>
	<p>Manufacturer Part Number: EL9110IU-T13</p> <hr/> <p>Manufacturer/Brand: Intersil</p> <hr/> <p>Part of Description: IC DIFF RCVR/EQUALZR SGL 16-QSOP</p> <hr/> <p>Datasheets:  EL9110IU-T13.pdf</p> <hr/> <p>RoHs Status: Contains lead / RoHS non-compliant</p> <hr/> <p>Stock Condition: New original, Stock Available.</p> <hr/> <p>Ship From: Hong Kong</p> <hr/> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
	
<p>Image may be representation. See specs for product details.</p>	









Specifications

Part Number	EL9110IU-T13
Manufacturer	Intersil
Description	IC DIFF RCVR/EQUALZR SGL 16-QSOP
Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Receiver
Package / Case	16-SSOP (0.154", 3.90mm Width)
Supplier Device Package	16-QSOP
Voltage - Supply	5V
Protocol	-
Number of Drivers/Receivers	0/1
Duplex	-
Data Rate	-
Packaging	Tape & Reel (TR)

EL9110IU-T13 is New Original in Stock, Search EL9110IU-T13 Datasheets, PDF, Inventory at Y-IC.com Online, Order EL9110IU-T13 Intersil with warrantied and confidence. RFQ EL9110IU-T13 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>EL9110IUZE9049 Intersil IC RECEIVER/EQUALIZER DIFF 16QSOP</p>	 <p>EL9110IU-T7 Intersil IC RCVR/EQLZR DIFF 150MHZ 16QSOP</p>	 <p>EL91 MURATA MURATA QFN12</p>	 <p>EL9110IUZ-T13 Intersil IC DIFF RCVR/EQUALZR SGL 16- QSOP</p>
 <p>EL9110IU Intersil IC RCVR/EQLZR DIFF 150MHZ 16QSOP</p>	 <p>EL91042001 Agastat Relays / TE Connectivity HEATSHRINK 0.205" X 4" BLACK</p>	 <p>EL91001B ELMOS ELMOS SOP-20</p>	 <p>EL9110IUZ Intersil IC RECEIVER/EQUALIZER DIFF 16QSOP</p>

Hot Parts

More

- | | | | | |
|-------------------|-------------------------|------------------------|------------------------|------------------------|
| ⚙️ 1210YC684KAT2A | ➡️ 18121A562FAT2A | ➡️ 1812AC471MAT3A | D 6DI100A-050P | ➡️ 6RI30G-180 |
| ⚡ AM79C940BVC | ⚙️ AOTF296L | D AP130-35WL-7 | ➡️ APL1085-33GC-TR | ➡️ APT5022JN |
| ⚙️ ATS177-WLA | ⚡ BZX84-C75/WA1 | ⚙️ C0603X5R0J474K030BC | ➡️ C0603X5R1A104K030BC | ➡️ C4532X7R1H335M200KA |
| D CC2430ZF128RTCR | ⚙️ CGA2B3X5R1V103M050BB | ⚡ CK45-E3DD222ZYVN | ⚙️ CRCW08058660FT | ➡️ F6KA2G436A4VE |
| ➡️ FOD617A300 | ➡️ FQU10N20 | ⚙️ FZT851TA | ⚡ GA342QR7GD221KW01L | ➡️ ICS952302AGLFT |
| ➡️ IDT82P2288BB | ➡️ ILC7071AIM528X | D IRFS4615 | ⚙️ IXDI502PI | ⚡ LDA313G8813F-245 |
| ⚙️ LEF75G602 | D LF444CDR2 | ➡️ LTC1474CS8 | ➡️ M5M5256FP-10LL | ➡️ MAX652CSA+T |
| ⚡ MAX807NCWE | ⚙️ MAX8863SEUK | ➡️ MBRM760-13 | ➡️ PE014005 | ➡️ SKKQ430/14E |
| ⚙️ SM06B-XSRK-ETB | ⚡ SR4D4024 | ⚙️ SSM6L13TU | D ST2310RES | ➡️ T40012220600 |
| ➡️ TCA9554ADBQR | ⚙️ TD46F10KFL | ⚡ UGN3503U | ⚙️ VLZ3V6B-GS08 | ➡️ Z86E0208SEC |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited