


	<p>S-80821CNPF-B8GTFU</p>
	<p>Manufacturer Part Number: S-80821CNPF-B8GTFU</p>
	<p>Manufacturer/Brand: SII Semiconductor Corporation</p>
	<p>Part of Description: IC VOLT DETECTOR 2.1V SNT-4A</p>
	<p>Datasheets:  S-80821CNPF-B8GTFU.pdf</p>
	<p>RoHs Status:  Lead free / RoHS</p>
	<p>Stock Condition: Compliant New original, Stock Available.</p>
	<p>Ship From: Hong Kong</p>
<p>Image may be representation. See specs for product details.</p>	<p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>

Specifications

Part Number	S-80821CNPF-B8GTFU
Manufacturer	SII Semiconductor Corporation
Description	IC VOLT DETECTOR 2.1V SNT-4A
Category	Integrated Circuits (ICs) > PMIC - Supervisors
Part Status	Require For Quote & Check Stock
Series	S-808xxC
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Type	Voltage Detector
Package / Case	4-SMD, Flat Leads
Supplier Device Package	SNT-4A
Output	Open Drain or Open Collector
Reset	Active Low
Number of Voltages Monitored	1
Reset Timeout	-
Voltage - Threshold	2.1V
Packaging	Tape & Reel (TR)

S-80821CNPF-B8GTFU is New Original in Stock, Search S-80821CNPF-B8GTFU Datasheets, PDF, Inventory at Y-IC.com Online, Order S-80821CNPF-B8GTFU SII Semiconductor Corporation with warrantied and confidence. RFQ S-80821CNPF-B8GTFU : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>S-80821CNMC-B8GT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.1V SOT23-5</p>	 <p>S-80821CNUA-B8GT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.1V SOT89-3</p>	 <p>S-80821CNNB-B8G-T2 SEIKO SEIKO SC-82AB</p>	 <p>S-80821CNUA-B8GT2G SII Semiconductor Corporation IC VOLT DETECTOR 2.1V SOT89-3</p>
 <p>S-80821CNUA-B8G-T2 SEIKO S-80821CNUA-B8G-T2 SEIKO</p>	 <p>S-80821CNY-B2-U SII Semiconductor Corporation IC VOLT DETECTOR 2.1V TO-92</p>	 <p>S-80821CNNB-B8GT2U SII Semiconductor Corporation IC VOLT DETECTOR 2.1V SC-82AB</p>	 <p>S-80821CNNB-B8GT2G SII Semiconductor Corporation IC VOLT DETECTOR 2.1V SC-82AB</p>

Hot Parts

More

- | | | | | |
|----------------------|--------------------|--------------------|----------------------|-----------------------|
| ⚙️ 06035U3R3JAT2A | 🔌 12067A3R3BAT2A | ➡️ 123NQ100R | D 23SR2KLFTR | ➡️ ACPM-5011-TR1 |
| ⊖ ADM202JNZ | ⚙️ AGPS-F001-TR1 | D AP8802FNG-7 | ➡️ AZ1117EH-1.2TRG1 | ➡️ BSS138-NL |
| ⚙️ F2412D-W25 | ⊖ FDG311N_NL | ⚙️ FESB16FT | 🔌 GJM1555C1H2R1BB01D | ➡️ GQM1875C2E7R0CB12D |
| D GRM0225C1E8R7DDAEL | ⚙️ HCPL0661R2 | ⊖ HIN207EIB | ⚙️ HPY1105W-TR | ➡️ HSMP-386F-TR1G |
| ➡️ ICS9169CM-23 | 🔌 IPD06N03LZ | ⚙️ IPS1011SPBF | ⊖ LC573010A-1D71 | ➡️ LD035A8R2CAB2A |
| 🔌 LP8720TLX-B | ➡️ LTC1407IMSE | D M57140-01 | ⚙️ MAX771ESA+T | ⊖ MC9S08FL16CLC |
| ⚙️ MM3464A15NRE | D N2293VF180 | ➡️ NCP700BMT33TBG | 🔌 NFA21SL157X1A48L | ➡️ NJU4069UBD |
| ⊖ PT2221-002 | ⚙️ SD25-1950R9UBQ1 | 🔌 SIP41109DY-T1-E3 | ➡️ SM6A24NSU | ➡️ TD420N08KOF |
| ⚙️ TL3842DR-8 | ⊖ TL431AIDBZRG4 | ⚙️ TML05124 | D TORX179S | ➡️ TS80C32X2-MCB |
| 🔌 TZM5241B-GS08 | ⚙️ UC29432D | ⊖ XI-910113 | ⚙️ XRP6124ES0.5TR-F | ➡️ ZHC2206-11 |

Contact us: Info@Y-IC.com

ADD:Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited