









	<h2 style="color: #E67E22;">ZL40207LDF1</h2>	
	Manufacturer Part Number:	ZL40207LDF1
	Manufacturer/Brand:	Microsemi
	Part of Description:	IC CLK BUFFER 1:8 750MHZ 32QFN
	Datasheets:	1.ZL40207LDF1.pdf 2.ZL40207LDF1.pdf 3.ZL40207LDF1.pdf
RoHS Status:	 Lead free / RoHS	
Stock Condition:	Compliant New original, Stock Available.	
Ship From:	Hong Kong	
Shipment Way:	DHL/Fedex/TNT/UPS/EMS	
Image may be representation. See specs for product details.		

Specifications

Part Number	ZL40207LDF1
Manufacturer	Microsemi
Description	IC CLK BUFFER 1:8 750MHZ 32QFN
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers,
Part Status	Require For Quote & Check Stock
Series	-
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Type	Fanout Buffer (Distribution)
Frequency - Max	750MHz
Package / Case	32-VFQFN Exposed Pad
Supplier Device Package	32-QFN (5x5)
Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.465 V
Output	LVPECL
Input	CML, HCSL, LVCMOS, LVDS, LVPECL
Ratio - Input:Output	1:8
Differential - Input:Output	Yes/Yes
Packaging	Tape & Reel (TR)

ZL40207LDF1 is New Original in Stock, Search ZL40207LDF1 Datasheets, PDF, Inventory at Y-IC.com Online, Order ZL40207LDF1 Microsemi with warrantied and confidence. RFQ
 ZL40207LDF1 : Info@Y-IC.com

You May Be Also Be interested

<p>In:</p>  <p>ZL40205LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>	 <p>ZL40206LDF1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40206LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40205LDF1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>
 <p>ZL40204LDG1 Microsemi IC CLK BUFFER 1:6 750MHZ 32QFN</p>	 <p>ZL40207LDG1 Microsemi IC CLK BUFFER 1:8 750MHZ 32QFN</p>	 <p>ZL40208LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>	 <p>ZL40209LDG1 Microsemi IC CLK BUFF MUX 2:6 750MHZ 32QFN</p>

Hot Parts

More

- | | | | | |
|-----------------------|----------------------|-------------------------|-----------------------|-------------------------|
| ⚙️ 06035C101KAT2A | ➡️ 08051C103J4T4A | ➡️ 08052A100GAT2A | D 1812AC103KAT1Q | ➡️ A2412D-1W |
| ⚡️ ADG409BR-REEL | ⚙️ AFT27S006NT1 | D AOZ1068DI | ➡️ AP431SAG-7 | ➡️ BStP6440K |
| ⚙️ BZT03C15-TR | ⚡️ CC0402JRNPO9BN111 | ⚙️ CGA4J2X7R2A223K125AA | ➡️ CNY17-3-W00E | ➡️ CS6-06I02 |
| D DG411DY-T | ⚙️ EFCH897MTDF1 | ⚡️ GN01048BOL | ⚙️ GRM21BR61C394KA01L | ➡️ HCTL-2016#PLC |
| ➡️ IDT75T512S125BS | ➡️ IRKT57-16 | ⚙️ LC1608TR10J | ⚡️ LM3495MTC | ➡️ LM3722IM5-4.63 |
| ➡️ LT3082EDD#PBF | ➡️ LTM2883Y-5S | D MACH111-7JC-10JI | ⚙️ MAX1812EUB+T | ⚡️ MC3356DWR2 |
| ⚙️ MT5330AKR | D N1042LC180 | ➡️ N740CH08 | ➡️ NEO-M8L-0-01 | ➡️ NTB0104UK |
| ⚡️ NTHS4501NT1 | ⚙️ PI3HDMI201ZFEX | ➡️ PVZ2A102A01R00 | ➡️ R2714ZD14J | ➡️ S-80930CNPF-G80TFG |
| ⚙️ S-8520B32MC-ARR-T2 | ⚡️ SAF-XC836-2FRIAB | ⚙️ SI1021R-T1-E3 | D SKKH71/08E | ➡️ SLF12575T-100M5R4-PF |
| ➡️ SQCSVA0R2BAT1A | ⚙️ TCM2010-441-4P-T | ⚡️ V300C12C75AN2 | ⚙️ V300C28C150BN | ➡️ VI-BN1-EV |

Contact us: **Info@Y-IC.com**

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited