










	<h2 style="color: red;">B65806D2005X000</h2>	
	<b>Manufacturer Part Number:</b>	<a href="#">B65806D2005X000</a>
	<b>Manufacturer/Brand:</b>	<a href="#">EPCOS</a>
	<b>Part of Description:</b>	INSULATING WASHER RM 5
<b>Datasheets:</b>	 <a href="#">B65806D2005X000.pdf</a>	
<b>RoHs Status:</b>	 Lead free / RoHS Compliant	
<b>Stock Condition:</b>	New original, 2500 pcs Stock Available.	
<b>Ship From:</b>	Hong Kong	
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

### Specifications

Part Number	B65806D2005X000
Manufacturer	EPCOS
Description	INSULATING WASHER RM 5
Category	<a href="#">Magnetics - Transformer, Inductor Components &gt;</a>
Part Status	2500 pcs Stock
Manufacturer Standard Lead Time	7 Weeks
Detailed Description	Supplier Device Package RM 5
Series	B65806
Accessory Type	Insulating Washer
For Use With/Related Products	RM
Supplier Device Package	RM 5
Lead Free Status / RoHS Status	Lead free / RoHS Compliant
Moisture Sensitivity Level (MSL)	1 (Unlimited)
Other Names	495-5217

B65806D2005X000 is New Original in Stock, Search B65806D2005X000 Datasheets, PDF, Inventory at Y-IC.com Online, Order B65806D2005X000 EPCOS with warrantied and confidence. RFQ B65806D2005X000 : [Info@Y-IC.com](mailto:Info@Y-IC.com)

### You May Be Also Be interested In:

 <p><b>B65806N1105D001</b> EPCOS COIL FORMER RM5 SUMIKON PM 9630</p>	 <p><b>B65805PR87</b> Epson FERRITE CORE RM 2.4UH N87 2PCS</p>	 <p><b>B65806B2203X000</b> EPCOS CLAMP RM 5</p>	 <p><b>B65806J2204X000</b> EPCOS CLAMP RM 5</p>
 <p><b>B65806D2005X000</b> EPCOS EPCOS NA</p>	 <p><b>B65806N1106D001</b> EPCOS COIL FORMER RM5 SUMIKON PM 9630</p>	 <p><b>B65806A5000X000</b> EPCOS INSULATING WASHER RM 5</p>	 <p><b>B65805P0160A045</b> EPCOS FERRITE CORE</p>

### Hot Parts

[More](#)

⚙️ 0603YC473KAT4A	➡️ 195D226X9020ZT 22UF 10% 20V ➡️ 2MBI600U4G-170A	D AQW216HAXC88	➡️ B652F-2T
⌚ B653F-2T	⚙️ B654F-2T	D B65806D2005X000	➡️ C1005JB1H473K050BB
⚙️ CBS50482R5	⌚ CL10B104K08NFNC	⚙️ CLS5D11HPNP-6R8NC	➡️ CY8C27243-24SXIT
D DTA115TETL	⚙️ EMA09N03AN	⌚ EPC1PI8N	➡️ FSA832L10X
➡️ GBPC2510	➡️ HFI-160808-56NJ-RT	⚙️ IQIG55S160C3	➡️ LQG15HS27NS02D
➡️ LQW04AN19NH00D0X	➡️ LTC2449IUHF#PBF	D LTC3114EFE-1#PBF	⌚ MAX8868EUK50+T
⚙️ MB39A138PFT-G-JN-ERE1	D MC14072BFEL	➡️ PM10VMA060	➡️ RJK0392DPA-02#J53
⌚ S-80833CNMC-B8S-T2	⚙️ S1F75510M0A010B	➡️ SAFEA707MAA8F0AR15	➡️ SN74ALS273NSR
⚙️ SP706EN-L/TR	⌚ SR100L-2R	⚙️ T55B157M6R3C0070	➡️ TLZ6V8B-GS18
➡️ UMK107F104ZA-T	⚙️ UWS2412	⌚ VI-201-10	➡️ XC6202PD02MR
		➡️ WGI218LM	

Contact us: [Info@Y-IC.com](mailto:Info@Y-IC.com)

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.  
Copyright © 2019 YIC International Co., Limited